

ESTIMATE

12/11/2024

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

Steve (LKK)
20/11/24, 3.34pm
m n
L/S
4 d j j

Vehicle No: YN9642T
Vehicle Model: ISUZU LORRY
Est No: CBMQ24110051
Claims ref:
Accident Date: 30/10/24
In Charge: BRIAN
Remarks:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	TAILLAMP LH/RH <i>BR</i>	1 <i>z</i>	PC \$ 250.00	\$ 500.00 <i>270 /</i>
2	TAILLAMP RH, COVER <i>x nn</i>	1	PC \$ 25.00	\$ 25.00
3	REAR DECK GATE <i>DD</i>	1	PC \$ 1,250.00	\$ 1,250.00 <i>1000 /</i>
4	RH DROP SIDE <i>(side gate) DD</i>	1	PC \$ 1,650.00	\$ 1,650.00 <i>1400 /</i>
5	LH LOCKER <i>BT</i>	1 <i>(refer to photo)</i>	PC \$ 220.00	\$ 220.00 <i>180 /</i>
<i>Scene photo damaged</i>				
LIST TOTAL S\$				\$ 3,645.00 <i>2800</i>
15% DISCOUNT S\$				\$ (546.75) <i>-15%</i>
				<u>\$ 3,098.25</u> <i>2380</i>

SPECIAL NET ITEMS:				
1	REVERSE SENSOR <i>x nn</i>	1	PC \$ 200.00	\$ 200.00
2	60KM/H DECAL <i>mc</i>	1	PC \$ 40.00	\$ 40.00 <i>25 /</i>
3	6 PAX DECAL <i>mc</i>	1	PC \$ 40.00	\$ 40.00 <i>25 /</i>
4	TAILGATE COMPANY LOGO <i>mc</i>	1	PC \$ 180.00	\$ 180.00 <i>150 /</i>
5	SIDEGATE COMPANY LOGO <i>mc</i>	1	PC \$ 250.00	\$ 250.00 <i>200 /</i>
6	TAILGATE CHECKER PLATE <i>BT</i>	1	PC \$ 550.00	\$ 550.00 <i>400 /</i>
7	RIVET SET <i>mc</i>	1	PC \$ 40.00	\$ 40.00 <i>30 /</i>
8	REAR BUMPER <i>x R</i>	1	PC \$ 650.00	\$ 650.00
9	REFLECTIVE STICKER <i>x nn</i>	1	PC \$ 40.00	\$ 40.00

SPECIAL NET TOTAL S\$ \$ 1,990.00 *830*

LABOUR CHARGE:				
1	TO PANEL BEAT/ KNOCKING AND REPLACE DAMAGED PARTS. TO REALIGN ALL THE CONNECTION			\$ 800.00 <i>500</i>
2	TO SPRAY PAINT ON REAR DECK GATE, DROP SIDE, REAR BUMPER			\$ 650.00 <i>550</i>
3	TO APPLY ANTI RUST PROOFING ON AFFECTED AREAS			\$ 80.00 <i>30</i>
4	TO TRANSFER RH DROP SIDE CHECKER PLATE			\$ 150.00 <i>80</i>
5	TO INSTALL TAILLAMP AND FUNCTIONING CHECK			\$ 40.00 <i>x</i>

ESTIMATE

12/11/2024

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

Vehicle No: YN9642T
Vehicle Model: ISUZU LORRY
Est No: CBMQ24110051
Claims ref:
Accident Date: 30/10/24
In Charge: BRIAN
Remarks:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
	TOTAL LABOUR COST S\$			<u>\$ 1,720.00</u>

AMOUNT S\$ \$ 6,808.25
GST @ 9% \$ 612.74
AMOUNT DUE S\$ \$ 7,420.99

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

4370

L/S - 3496
= 3500