



DICKSON GROUP
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

QUOTATION

QUOTATION FOR

NAME: India International Insurance Pte Ltd
COMPANY NAME: India International Insurance Pte Ltd
STREET ADDRESS: 64 Cecil Street, #04/#05-02, IOB Building
POSTAL CODE: Singapore 049711
PHONE: 6347 6100

DATE: 12/11/2024

REF: SD0B24BB0001
VEHICLE NO: SMR1110K
MAKE: JAGUAR
MODEL: XE
PREPARED BY: XIANG

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	LABOUR						
1	TO REMOVE & REPLACE BUMPER FRONT, HEADLAMP ASSY RH & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	1		\$400.00	\$ 400.00		\$ 400.00
2	TO SPRAY BUMPER FRONT	1		\$300.00	\$ 300.00		\$ 300.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	1		\$100.00	\$ 100.00		\$ 100.00
4	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	1		\$150.00	\$ 150.00		\$ 150.00
5	TO CARRY OUT BODY CAVITY PRESERVATION	1		\$100.00	\$ 100.00		\$ 100.00
6	TO TRANSFER SENSORS FRONT	1		\$100.00	\$ 100.00		\$ 100.00
	PARTS						
1	BUMPER FRONT	1		\$3,750.00	\$ 3,750.00		\$ 3,750.00
2	BUMPER CLIPS	10		\$15.00	\$ 150.00		\$ 150.00
3	HEADLAMP ASSY RH	1		\$4,050.00	\$ 4,050.00		\$ 4,050.00
4	BUMPER SIDE RETAINER FRONT RH	1		\$157.50	\$ 157.50		\$ 157.50
5	SENSOR BRACKET FRONT	4		\$50.00	\$ 200.00		\$ 200.00
SUBTOTAL					\$ 9,457.50	SUBTOTAL	\$ 9,457.50
GST 9%					\$ 851.18	GST 9%	\$ 851.18
TOTAL					\$ 10,308.68	TOTAL	\$ 10,308.68

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD



(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)