

ESTIMATE REPORT

ATTN: MOTOR CLAIMS DEPT

VRN
MODEL

SFY56L
HONDA CIVIC

Not Authorized
90096608
27/6/24
2/5 \$2800/
Emph. After 4 days.

PARTS REPLACEMENT	Qty	S\$ Unit	S\$ Amt
1 Bootlid	1	\$724.70 760.10	\$ 760.10
2 Bootlid hinge RH	1	\$ 54.20	\$ 54.20
3 Bootlid hinge LH	1	\$ 54.20	\$ 54.20
4 Bootlid lock	1	\$ 90.40	\$ 90.40
5 Bootlid weatherstrip	1	\$ 70.40	\$ 70.40
6 Bootlid emblem - Carbon Fiber	1	\$ 246.60	\$ 246.60
7 Bootlid inner trim	1	\$ 49.90	\$ 49.90
8 Bootlid third brake lamp	1	\$ 96.30	\$ 96.30
9 Bootlid Center garnish	1	\$ 121.80	\$ 121.80
10 Bootlamp RH	1	\$ 148.20	\$ 148.20
11 Bootlamp LH	1	\$ 148.20	\$ 148.20
12 Taillamp outer RH	1	\$ 316.20	\$ 316.20
13 Taillamp outer LH	1	\$ 316.20	\$ 316.20
14 Rear bumper	1	\$ 617.20	\$ 617.20
15 Rear bumper side retainer RH	1	\$ 21.50	\$ 21.50
16 Rear bumper side retainer LH	1	\$ 21.50	\$ 21.50
17 Rear bumper bracket RH	1	\$ 12.70	\$ 12.70
18 Rear bumper bracket LH	1	\$ 12.70	\$ 12.70
19 Rear Parking Sensor RH outer	1	\$ 266.20	\$ 266.20
20 Rear Parking Sensor RH inner	1	\$ 266.20	\$ 266.20
21 Rear Parking Sensor LH outer	1	\$ 266.20	\$ 266.20
22 Rear Parking Sensor LH inner	1	\$ 266.20	\$ 266.20
23 Rear Parking Sensor Holder RH outer	1	\$ 72.60	\$ 72.60
24 Rear Parking Sensor Holder RH inner	1	\$ 72.60	\$ 72.60
25 Rear Parking Sensor Holder LH outer	1	\$ 72.60	\$ 72.60
26 Rear Parking Sensor Holder LH outer	1	\$ 72.60	\$ 72.60
27 Rear bumper reinforcement	1	\$ 199.20	\$ 199.20
28 Rear bumper reflector RH	1	\$ 29.20	\$ 29.20
29 Rear bumper reflector LH	1	\$ 29.20	\$ 29.20
30 Rear bumper lower chrome	1	\$ 136.20	\$ 136.20
31 Rear end panel	1	\$ 294.25	\$ 294.25
32 End panel top garnish	1	\$ 60.30	\$ 60.30
33 End panel antenna	1	\$ 64.70	\$ 64.70
34 End panel buzzer	1	\$ 80.10	\$ 80.10
35 Rear fender inner trim RH	1	\$ 70.10	\$ 70.10
36 Rear fender inner trim LH	1	\$ 70.10	\$ 70.10
37 Rear fender RH	1	\$ 861.20	\$ 861.20
38 Rear fender LH	1	\$ 861.20	\$ 861.20
39 Spare tyre panel	1	\$ 362.40	\$ 362.40
40 Spare tyre compartment box	1	\$ 66.10	\$ 66.10

\$ 7,697.75

\$ 1,539.55

\$ 6,158.20

All List -20%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Special Nett

19 rear number plate with casing	1	\$	80.00	\$	Daye	80.00	35
20 rear bumper clips (set)	1	\$	80.00	\$	111	80.00	30
21 end panel top garnish clips (set)	1	\$	80.00	\$	17	80.00	x
22 sealant - body joint	1	\$	80.00	\$	17	80.00	x
23 bootlid inner board clips (set)	1	\$	80.00	\$	17	80.00	x
24 bootlid top spoiler	1	\$	580.00	\$	17	580.00	x

25 Rear bumper side spoiler 1set CR2 \$250 ✓ S/N

\$ 980.00

PARTS TOTAL \$ 7,138.20

Labour Charges

1 Remove, repair and replace parts for the effected areas.	\$	1,600.00	600
2 Putty, Blend And Spray Paint.	\$	1,500.00	800
3 Check wiring, re-align taillamps.	\$	80.00	20
4 Remove and reinstall cushions, seats, backrests, inner trim, garnish, roof lining and/or upholstery to facilitate repair.	\$	150.00	60
5 Remove and refit rear end panel lining and garnish to facilitate repair.	\$	150.00	2
6 Remove and reinstall rear trim compartment.	\$	150.00	2
7 Dismantle and transfer Bootlid fittings and mechanism to new Bootlid to facilitate repair.	\$	180.00	50
8 Remove and reinstall rear bumper sensors.	\$	120.00	30

No. of repair days: 12

LABOURS TOTAL \$ 3,930.00

Grand Total : \$ 11,068.20
Add 9% GST : \$ 996.14
Nett Total : \$ 12,064.34

P-204420
202
1635.36
315
1560
3510.36
202
2808