

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Melvin Ye Yongkang

Date: 04 Jul 2024

**Preliminary Advice**

Insured Vehicle No : SLQ7389B  
TP Vehicle No : SFY56L  
Make : HONDA CIVIC  
Date of Inspection : 27/06/2024  
Inspection At : S M SPRAY PAINTING PTE LTD  
25 KAKI BUKIT ROAD 4  
#08-30 SYNERGY @ KB  
SINGAPORE 417800

Accident Date : 24/06/2024  
Assignment Date : 26/06/2024  
Est. Duration of Repair : 4

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,318.20
Revised Amount	:S\$	3,510.36
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,510.36
Lump Sum Repair	:S\$	2,800.00

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	48,303.00
Salvage Value	:S\$	
Margin for Repair	:S\$	66,697.00

**Remarks**

- ( ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( ) Part-by-Part repair  
 ( X ) Lump Sum repair
- ( X ) The above survey was conducted on a 'without prejudice' basis.  
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.