



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 4590L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	495.60	495.60
2	REAR BUMPER SIDE HOLDER @\$92.30	NOT NECESSARY	184.60	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	329.60	-
2	REAR BUMPER REINFORCEMENT STAY @\$145.80	NOT NECESSARY	291.60	-
5	REAR BUMPER REINFORCEMENT BRACKET @\$18.00	NOT NECESSARY	90.00	-
1	REAR BUMPER REINFORCEMENT ANTENNA SENSOR	NOT NECESSARY	195.50	-
2	REAR BUMPER SIDE UNDERCOVER @\$98.60	NOT NECESSARY	197.20	-
2	REAR BUMPER REFLECTOR @\$72.50	CRACKED	145.00	145.00
	LESS 20% DISCOUNT		-385.82	-128.12
			1,543.28	512.48
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER LOWER GARNISH (SN)	TORN	600.00	300.00
2	SET REAR BUMPER SIDE UNDERCOVER CLIPS @\$20.00 (SN)	NOT NECESSARY	40.00	-
1	SET REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
			950.00	530.00
<b><u>LABOUR</u></b>				
	PANEL BEATING, REMOVE AND REFIT PARTS.		500.00	200.00
	SPRAY PAINTING TO AFFECTED AREA.		400.00	200.00
	WIRING CHECK.	NOT NECESSARY	50.00	-
	TO REMOVE REVERSE SENSOR.		100.00	50.00
			1,050.00	450.00
<b>GRAND TOTAL</b>			<b>3,543.28</b>	<b>1,492.48</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,100.00</b>
---	--	--	-----------------

Report Ref No. CS/INC24110232/Avh3m4(N)

TOTAL FOR SPARE PARTS: \$ 2,493.28 \$ 1,042.48  
TOTAL FOR LABOUR : \$ 1,050.00 \$ 450.00  
TOTAL REPAIR COST: \$ 3,543.28 \$ 1,492.48

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.