

ADVANCE AUTO GARAGE

TO	: NTUC	DATE	12/11/2024
VEHICLE NO	: SMD4590L (2018)	<i>Veron</i>	
VEHICLE MODEL	: HYUNDAI ELANTRA		
CHASSIS NO	: KMHD841CMJU729455		

CLAIM DETAILS: PARTS		QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Debond</i>	1	\$ 495.60	\$ 495.60
2	REAR BUMPER SIDE HOLDER <i>NEW</i>	2	\$ 92.30	\$ 184.60
3	REAR BUMPER REINFORCEMENT	1	\$ 329.60	\$ 329.60
4	REAR BUMPER REINFORCEMENT STAY <i>NEW</i>	2	\$ 145.80	\$ 291.60
5	REAR BUMPER REINFORCEMENT BRACKET	5	\$ 18.00	\$ 90.00
6	REAR BUMPER REINFORCEMENT ANTENNA SENSOR <i>NEW</i>	1	\$ 195.50	\$ 195.50
7	REAR BUMPER SIDE UNDERCOVER <i>NEW</i>	2	\$ 98.60	\$ 197.20
8	REAR BUMPER REFLECTOR <i>could</i>	2	\$ 72.50	\$ 145.00
TOTAL PRICE:				\$ 1,929.10
LESS 20%:				\$ 385.82
SUB TOTAL PRICE:				\$ 1,543.28

640.60
512.48

SPECIAL NETT ITEMS		QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>NEW</i>	1 SET	\$ 30.00	\$ 30.00
2	REAR BUMPER LOWER GARNISH <i>form</i>	1	\$ 600.00	\$ 600.00
3	REAR BUMPER SIDE UNDERCOVER CLIPS <i>NEW</i>	2 SETS	\$ 20.00	\$ 40.00
4	REVERSE SENSOR <i>Dave</i>	1 SET	\$ 280.00	\$ 280.00
TOTAL:				\$ 950.00

530

LABOUR		PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 800.00	<i>200</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 400.00	<i>200</i>	
3	WIRING CHECK	\$ 50.00	<i>X</i>	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
TOTAL:		\$ 1,050.00		<i>450.</i>

ESTIMATE REPORT

TOTAL PARTS COST:	\$ 2,493.28
TOTAL LABOUR COST:	\$ 1,050.00
TOTAL REPAIR COST:	\$ 3,543.28

Total: 149248
L/S: 1.11c

02 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____