

JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #01-77 AUTOBAY@KAKI BUKIT

SINGAPORE 417883

TEL: 92327457

TO	: NTUC	DATE 12/11/2024
VEHICLE NO	: FBG3386G (2022)	<i>Xiao Chen.</i>
VEHICLE MODEL	: YAMAHA NMAX	
CHASSIS NO	: MH3SG5680NK130541	

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	FRONT WINDSHIELD <i>lt</i>		320.00	<i>✓ 160</i>
2	HEADLAMP <i>Cracked</i>		1100.00	<i>✓ 683</i>
3	HEADLAMP BRACKET <i>new</i>		155.00	<i>+</i>
4	HEADLAMP TOP COVER <i>Cracked</i>		265.00	<i>✓</i>
5	HEADLAMP LOWER COVER <i>new</i>		135.00	<i>✓</i>
6	HEADLAMP SIDE COVER @265 <i>Cracked RH</i>		530.00	<i>✓ 265</i>
7	FRONT COWLING SIDE (BLACK) @189 <i>RH ut</i>		378.00	<i>✓ 189</i>
8	FRONT SIGNAL LAMP @130 <i>Not new</i>		260.00	<i>X</i>
9	YAMAHA LOGO @25 <i>Not new</i>		50.00	<i>X</i>
10	FRONT FENDER <i>ut</i>		160.00	<i>✓ 85</i>
11	FRONT FORK @660 <i>Best</i>		1320.00	<i>✓</i>
12	FRONT FORK UNDER BRACKET <i>new</i>		280.00	<i>✓</i>
13	FRONT BRAKE DISC <i>ut</i>		125.00	<i>✓</i>
14	BRAKE LEVER @38 <i>RH ut</i>		76.00	<i>✓ 38</i>
15	FRONT WING MIRROR @52 <i>RH missing</i>		104.00	<i>✓ 52</i>
16	FRONT WHEEL RIM <i>3 new</i>		580.00	<i>X</i>
17	FRONT WHEEL RIM SHAFT <i>3 new</i>		20.00	<i>X</i>
18	HANDLE BAR <i>Not new</i>		185.00	<i>✓</i>
19	BALANCER @45 <i>RH ut</i>		90.00	<i>✓ 45</i>
20	SPEEDOMETER <i>3 new</i>		610.00	<i>X</i>
21	SPEEDOMETER COVER <i>3 new</i>		320.00	<i>X</i>
22	FRONT INNER COVER <i>ut 3 new</i>		215.00	<i>✓</i>
23	FRONT INNER COVER GARNISH <i>new</i>		75.00	<i>+</i>
24	FRONT UNDER COVER <i>new</i>		380.00	<i>+</i>
25	STEP BOARD @290 <i>RH ut</i>		580.00	<i>✓ 290</i>
26	STEP BOARD COVER @96 <i>new</i>		192.00	<i>X</i>
27	REAR SIDE FAIRING @290 <i>Repair</i>		580.00	<i>+</i>
28	REAR SIDE FAIRING COVER @ 135 <i>RH ut</i>		270.00	<i>✓ 135</i>
29	NMAX LOGO @30 <i>3 new</i>		60.00	<i>+</i>
30	155 STICKER @15 <i>3 new</i>		30.00	<i>+</i>
31	REAR FOOT REST @58 <i>new</i>		116.00	<i>+</i>
32	REAR SWING ARM <i>new</i>		850.00	<i>+</i>
33	REAR EXHAUST MUFFLER <i>new</i>		558.00	<i>+</i>
34	REAR EXHASUT MFFLER COVER <i>ut</i>		97.00	<i>✓</i>
35	REAR MUDGUARD <i>3 new</i>		210.00	<i>X</i>
36	REAR MUDGUARD REFLECTOR @16 <i>3 new</i>		32.00	<i>+</i>

37	REAR MUDGUARD NUMBER PLATE LAMP	NEW	28.00	X
38	TAILLAMP	NEW	185.00	X
39	TAILLAMP LOWER COVER	NEW	76.00	X
40	RAER PASSENGER HANDLE BAR	NEW	165.00	X
41	REAR SHOCK ABSORBER @305	NEW	610.00	X
42	AIR CLEANER BOX	NEW	268.00	X
43	AIR CLEANER BOX OUTER COVER	NEW	126.00	X
44	ENGINE COVER	NEW	289.00	X 158
45	MAIN STAND	NEW	145.00	X
46	SIDE STAND	NEW	82.00	X
			13282.00	
less 10%			1328.20	10%
			11953.80	
			20.00	✓
			60.00	✓
			40.00	✓
			50.00	✓
			50.00	X
			150.00	X
			250.00	X 180
			90.00	✓
Total Parts			710.00	

SPECIAL NETT ITEMS

- FRONT NUMBER PLATE
- FRONT WHEEL BEARING SET
- FORK OIL
- FORK OIL SEAL
- REAR SWING ARM BUSH
- REAR THERMAL STORAGE BAG
- REAR THERMAL STORAGE BAG BRACKET
- STEERING CONE & BEARING

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
1	PANEL BEATING	600.00	250
2	SPRAY PAINTING	400.00	200
3	WIRING	50.00	30
4	TO REPAIR & STRAIGHTEN BODY CHASSIS	250.00	X
5	TO REMOVE REAR EXHAUST PIPE	120.00	X
6	TOWING FEES	40.00	✓
Labour Total :		1460.00	
TOTAL (PARTS & LABOUR):		14123.20	

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 4990.60

L/S: 3.9K.✓

04 Days