

PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G



PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G






LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 17)

PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G



PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G



PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G





PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G



PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G



PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 9 of 17)

PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G




PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G



PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G




PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G



PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G



PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G



PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G



PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G



PHOTOGRAPHS FOR VEHICLE NO. : FBG 3386G

