

WIKKY

bee GER

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SJB4856S

Make & Model: Toyota Fielder

Chassis number: NZE1419048549

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate	1	\$ bt / 910.00
2	Tailgate centre emblem	1	\$ nel / 55.00
3	Tailgate "Fielder" emblem	1	\$ nel / 42.00
4	Tailgate "X" emblem	1	\$ nel / 31.00
5	Tailgate weatherstrip	1	\$ fwi / 245.00
6	Tailgate lock	1	\$ X n / 322.00
7	Tailgate lock catch	1	\$ X n / 21.00
8	Tailgate inner trim board	1	\$ cne / 387.00
9	Rear bumper	1	\$ dis / 533.00
10	Rear bumper RH side retainer	1	\$ X n / 75.00
11	Rear bumper LH side retainer	1	\$ dis / 75.00
12	RH taillamp	1	\$ X / 607.00
13	RH taillamp lower bracket	1	\$ X / 68.00
14	RH taillamp panel	1	\$ X / 198.00
15	RH taillamp lock clips	1	\$ X / 44.00
16	LH taillamp	1	\$ tra / 607.00
17	LH taillamp lower bracket	1	\$ dis / 68.00
18	LH taillamp panel	1	\$ hti / 198.00
19	LH taillamp lock clips	1	\$ X n / 44.00
20	End panel	1	\$ bt / 506.00
21	End panel inner garnish	1	\$ dis / 233.00
22	Keyless sensor	1	\$ X n / 167.00
23	Rear LH fender	1	\$ buc / 986.00
24	Rear LH fender glass with rubber seal	1	\$ X n / 556.00
25	Rear LH fender inner trim board	1	\$ dp / 717.00
26	Rear LH fender splash shield	1	\$ fu / 292.00
27	Rear LH fender petrol cover	1	\$ X n / 95.00
28	Rear LH fender petrol garnish	1	\$ X n / 162.00
29	Rear LH fender inner panel	1	\$ x R / 635.00
30	Rear RH fender inner trim board	1	\$ X n / 717.00
31	Rear LH door	1	\$ Ry / 1,279.00
32	Rear LH door frame sticker	1	\$ X / 109.00
33	Rear LH door lock	1	\$ X / 331.00
34	Rear LH door inner trim board	1	\$ X / 683.00
35	Rear LH door weatherstrip	1	\$ X / 198.00
36	Rear axle beam	1	\$ X / 2,265.00
37	Rear LH bearing	1	\$ X / 442.00
38	Rear LH shock absorber	1	\$ X / 281.00

55 61.70

25% - 4171.27

			\$ 15,184.00
		Parts less 25%	\$ 3,796.00
		Total	\$ 11,388.00

No.	Special Nett Items	Qty	Amount S\$
1	Tailgate windscreen glass sealant	1	\$ 40.00 80.00
2	Tailgate windscreen glass inner seal	1	\$ 20.00 60.00
3	Tailgate inner trim board clips	1set	\$ 30.00 80.00
4	Taigate sealant	1	\$ X 100.00
5	Rear bumper clips	1set	\$ 20.00 80.00
6	Rear bumper reverse sensors	1set	\$ 200.00 350.00
7	End panel inner garnish clips	1set	\$ 4.00 60.00
8	End panel joint sealant	1	\$ 4.00 80.00
9	Rear RH fender inner trim board clips	1set	\$ X 80.00
10	Rear LH fender inner trim board clips	1set	\$ 30.00 80.00
11	Rear LH fender inner panel joint sealant	1	\$ X 100.00
12	Rear LH fender joint sealant	1	\$ 40.00 100.00
13	Rear LH fender glass sealant	1	\$ 40.00 80.00
14	Rear LH fender glass inner seal	1	\$ X 50.00
15	Roof lining clips	1set	\$ X 120.00

Total: \$ 1,500.00 500

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	1000 \$ 1,800.00
2	Spray painting on affected areas and panels	1000 \$ 1,600.00
3	Check wiring and lighting system on affected areas	30 \$ 120.00
4	Apply rust coating chemical on affected areas and panels	30 \$ 180.00
5	Remove and reinstall roof lining, seats ans carpet to assis repair	60 \$ 400.00
6	Remove and reinstall fuel tank, pipes, hoses and sensors to assist repair	60 \$ 220.00
7	Remove and reinstall rear LH fender glass to assist repair	60 \$ 120.00
8	Test drive and adjust wheel alignment system	\$ X 180.00
9	Remove and replace rear undercarriage parts to assist repair	\$ X 550.00
10	Remove and replace rear bumper reverse sensos to assist repair	20 \$ 100.00
11	Remvove and replace rear inner trims, garnish and boards to assist repair	60 \$ 280.00
12	Remove and reinstall tailgate windscreen glass to assist repair	120 \$ 240.00

13	Remove and reinstall tailgate inner mechanism to new tailgate	60	\$ 180.00
14	Remove and reinstall rear LH door inner mechanism to new door	111 X	\$ 150.00
Total:			\$ 6,120.00

2510

Agreed Amount: _____ (Part by Part / Lump sum)
Working days: _____

Spare Parts: \$ 11,388.00
Special Nett: \$ 1,500.00
Labour: \$ 6,120.00

Total Amount: \$ 19,008.00

Taufik 97495749
'wp' 25/8/22 @ 515 pm
L/S Resurvey after repair
taufik @ lkhaut.com
= 7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

4171-27
500
2510
7181-27
L/S \$5700
07 days
X