

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

LKK
not allowed
all
moss
13/11/24

5 days
4/s \$ 4500/-
unphoto Harry

Owner : Chia Chee Keong (91551066)

Accident Date : 31-Oct-24

Vehicle No : FBT1214P (COE: 171121-161131)

Vehicle Model : Yamaha Nmax
155 ABS
Connected

Estimated Repair Costs

Qty	Description	Amount S(\$)
	List Items	
1	Front fork assy	\$ 500 980.00 X
1	Fork under bracket	\$ 11 280.00 X
1	Front sport rim	\$ 11 650.00 X
1	Front brake disc	\$ 11 280.00 X
1	Front rim shaft	\$ 11 125.00 X
1	Front rim bearing	\$ 11 180.00 X
1	Windshield	280 \$ 11 380.00
1	Headlamp (LED)	\$ 11 980.00
1	Side mirror	90 \$ 11 180.00
1	Handle-bar	165 \$ 11 295.00
1	Handle-bar balancer set	48 \$ 11 125.00
1	Hand grip (1 set)	\$ 11 60.00 X
1	Brake levers (1 set)	110 \$ 11 180.00
1	Front signals - 1 set	\$ 11 295.00 X
1	Front side cover matt (1 set)	160 \$ 11 280.00
1	Exhaust assy	R \$ 11 850.00 X
1	Engine mounting	\$ 11 680.00 X
1	Air filter assy	305 \$ 11 400.00
1	Belt cover	166 \$ 11 200.00
1	Rear rim	\$ 11 680.00
1	Rear brake disc	\$ 11 320.00 X
1 suf	Rear absorber	\$ 11 580.00
1	Rear fender	162 \$ 11 255.00
1	Rear number plate lamp	90 \$ 11 255.00
2	Footstep panels	180 M/S \$ 11 380.00 lpc
2	Footstep lower cover	160 M/S \$ 11 320.00 lpc
1	Rear Footrest (1 set)	\$ 11 220.00 X
1	Rear lamp	320 \$ 11 520.00
1	Fairing cover (1 set)	980 \$ 11 1,320.00
		\$ 12,250.00
	Less 10%	\$ 1,225.00
		\$ 11,025.00

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Chia Chee Keong (91551066)

Accident Date : 31-Oct-24

Vehicle No : FBT1214P (COE: 171121-161131)

Vehicle Model : Yamaha Nmax
155 ABS
Connected

Estimated Repair Costs

Special Net Items

1 <i>Rear</i>	Number plate (1 set)	\$ <i>547</i>	38.00	<i>20</i>
2	Fork oils	\$ <i>11</i>	30.00	<i>X</i>
2	Fork oil seals	\$ <i>11</i>	56.00	<i>X</i>
1	Steering cone (1 set)	\$ <i>11</i>	120.00	<i>X</i>
1	Nmax logo	\$ <i>11</i>	100.00	<i>60</i>
1	Rear box	\$ <i>617</i>	480.00	<i>300</i>
1	Rear box bracket	\$ <i>11</i>	180.00	<i>X</i>
		\$	1,004.00	


S/No. Labour

1	To provide towing service (LOD) \$70.00	<i>refer to LOD</i>	\$	-	<i>X</i>
2	To check wiring and reset headlamp focusing		\$	<i>11</i>	80.00 <i>X</i>
3	To provide labour		\$		520.00 <i>380</i>
4	To repair body frame		\$	<i>11</i>	480.00 <i>X</i>
			\$		1,080.00

Grand Total

\$ 13,109.00

Singapore Dollars: Thirteen Thousand One Hundred and Nine only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 5456
102
4910.4
760