



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2501971

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 02/04/2025
Reference CD/LPC24110244/Epa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SNT 3410J
Insured Veh. SNF 7602U
Claim No. 24/24/24/VP05/030177
Policy No. Z24VP05035916
Accident Date 11/11/2024
Inspection Date 19/11/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CD/LPC24110244/Epa3q2(N) Date: 02/04/2025 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNF 7602U	Veh. Inspected	SNT 3410J
	Policy No.	Z24VP05035916	Coverage (\$)	0.00
	Claim No.	24/24/24/VP05/030177	Excess (\$)	0.00
	Assign From	GERALD	Assign Date	19/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	XPENG G6	c.c	0
	Engine No.	HIDDEN	Year of Reg.	2024
	Chassis No.	L1NNSGHA5RB074127	Colour	BLACK
	Odometer	1392 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/45 R20	MICHELIN	7 mm
	L/H Front Tyre	255/45 R20	MICHELIN	7 mm
	R/H Rear Tyre	255/45 R20	MICHELIN	7 mm
	L/H Rear Tyre	255/45 R20	MICHELIN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/11/2024	Inspection Date	19/11/2024
	Survey held at	XPREMIUM BEV PTE LTD 53 UBI ROAD 1 SINGAPORE 408698		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNT 3410J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER UPPER (SN)	NOT NECESSARY	773.00	-
1	REAR BUMPER LOWER (SN)	DEFORMED	773.00	773.00
1	REAR BUMPER SPOILER (SN)	CUT	387.00	387.00
1	REAR BUMPER REVERSE FOR LIGHT (RH) (SN)	CUT	248.00	248.00
2	REAR WHEEL ARCH TRIM -LH/RH (SN)	NECESSARY	350.00	350.00
1	SUNDRIES (SN)	NOT NECESSARY	500.00	-
			3,031.00	1,758.00
	<u>LABOUR</u>			
	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR .		360.00	360.00
	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED .		2,000.00	1,200.00
	TO RESPRAY REAR BUMPER ,REAR BUMPER MID ,REAR BUMPER SPOILER AND BOTH REAR WHEEL ARCH TRIMS .		4,200.00	1,800.00
	TO CARRY OUT DIAGNOSTIC CHECK .		480.00	480.00
			7,040.00	3,840.00
	GRAND TOTAL		10,071.00	5,598.00
	RECOMMENDED COST OF REPAIRS			5,598.00

Report Ref No. CD/LPC24110244/Epa3q2(N)

Market Value: \$200,000.00(est) less LTA Rebate: \$112,811.00(est) = Nett Value :\$87,189.00(est)

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNT 3410J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNT 3410J

RE-INSPECTION

