

OK

### CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6243 1373

Reg. No: 201538764H

Email: CA3SERVICES@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	12-11-24
CLAIM TYPE:	T/P CLAIM
TO:	INCOME
<b>VEHICLE DETAILS</b>	
VEHICLE NO:	SFW172U
MAKE & MODEL:	NISSAN KICKS
CHASSIS NO:	
<b>ACCIDENT DETAILS</b>	
DATE:	10 November, 2024
TIME:	1630HRS
THIRD PARTY REQUESTOR:	JACK LI

#### CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Dented</i>	1	\$ 3,522.30	\$ 3,522.30
2	TAIL GATE LOGO <i>new</i>	1	\$ 70.00	\$ 70.00
3	TAIL GATE E-POWER EMBLEM <i>new</i>	1	\$ 80.00	\$ 80.00
4	TAIL GATE KICKS EMBLEM	1	\$ 80.00	\$ 80.00
5	TAIL GATE LOCK <i>new</i>	1	\$ 335.00	\$ 335.00
6	TAIL GATE WEATHERSTRIP <i>new</i>	1	\$ 280.00	\$ 280.00
7	TAIL GATE LAMP <i>new</i>	2	\$ 530.00	\$ 1,060.00
8	TAILGATE INNER TRIM BOARD <i>new</i>	1	\$ 420.00	\$ 420.00
9	TAIL GATE INNER HANDLE <i>new</i>	1	\$ 150.00	\$ 150.00
10	TAIL GATE OUTER GARNISH <i>new</i>	1	\$ 520.00	\$ 520.00
11	TAIL GATE ANTENNA SWITCH <i>new</i>	1	\$ 195.00	\$ 195.00
12	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 222.30	\$ 222.30
13	REAR BUMPER <i>Dented</i>	1	\$ 1,255.30	\$ 1,255.30
14	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 62.40	\$ 124.80
15	REAR BUMPER REFLECTOR <i>Missing RH.</i>	2	\$ 95.00	\$ 190.00
16	REAR BUMPER SPONGE <i>new</i>	1	\$ 255.00	\$ 255.00
17	REAR BUMPER SENSOR <i>1 piece damaged</i>	4	\$ 280.00	\$ 1,120.00
18	REAR BUMPER SENSOR CAP <i>new</i>	4	\$ 30.00	\$ 120.00
19	TAILLAMP <i>new RH comb</i>	2	\$ 850.00	\$ 1,700.00
20	REAR FENDER INNER TRIM <i>new</i>	2	\$ 620.00	\$ 1,240.00
21	REAR END PANEL <i>Dented</i>	1	\$ 750.00	\$ 750.00

954

852

95

115

280

850

403

22	REAR END PANEL TOP GARNISH <del>new</del> <i>new</i>	1	\$ 230.00	\$ 230.00	<i>+</i>
23	REAR FLOOR PANEL <i>new</i>	1	\$ 1,455.20	\$ 1,455.20	<i>+</i>
24	REAR FLOOR PANEL TOP BAORD <i>new</i>	1	\$ 580.00	\$ 580.00	<i>+</i>
25	REAR FLOOR PANEL SPONGE <i>new</i>	1	\$ 450.00	\$ 450.00	<i>+</i>
26	REAR EXHAUST PIPE <del>Best</del> <i>Best</i>	1	\$ 980.00	\$ 980.00	<i>+</i>
27	REAR EXHAUST PIPE MOUNTING <i>rear trim</i>	1	\$ 90.00	\$ <del>90.00</del>	<i>+</i> 45
28	REAR EXHAUST PIPE HEAT SHEILD <i>new</i>	1	\$ 280.00	\$ 280.00	<i>+</i>

TOTAL PRICE \$ 17,754.90

LESS 10% \$ 1,775.49

SUB TOTAL PRICE \$ 15,979.41

*5026.30*  
*4523.67*

*7636.41*

**SPECIAL NETT ITEMS**

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
2	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 100.00	\$ 100.00	<i>60</i>
3	TAILGATE INNER TRIM CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00	<i>+</i>
4	REAR BUMPER CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00	<i>+</i>
5	REAR FENDER INNER TRIM CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00	<i>+</i>
6	REAR END PANEL TOP GARNISH CLIPS SET <i>new</i>	1	\$ 20.00	\$ <del>20.00</del>	<i>+</i>
7	REAR END PANEL INSULATION SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	<i>60</i>

TOTAL \$ 350.00

*140*

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 2,200.00	\$ 2,200.00	<i>700</i>
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 2,000.00	\$ 2,000.00	<i>800</i>
3	TUFF COAT	1	\$ 200.00	\$ 200.00	<i>60</i>
4	WIRING CHECK	1	\$ 80.00	\$ 80.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 280.00	\$ 280.00	<i>60</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00	<i>50</i>
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00	<i>50</i>
8	TRANSFER TAILGATE MECHANISM	1	\$ 120.00	\$ 120.00	<i>60</i>
9	REMOVE AND REFIX TAILGATE WINDSCREEN	1	\$ 140.00	\$ 140.00	<i>120</i>
10	REMOVE AND REFIX REAR EXHAUST PIPE	1	\$ 250.00	\$ 250.00	<i>60</i>

TOTAL \$ 5,470.00

*1990*

**ESTIMATE REPORT**

TOTAL PARTS COST	\$	16,329.41
TOTAL LABOUR COST	\$	5,470.00
TOTAL REPAIR COST	\$	21,799.41

**APPROVED DETAILS:**

SURVEYOR:  
 CONTACT NO.:  
 PART BY PART/LUMP SUM  
 NO. OF DAYS

Adrian Ly  
 x/s 12/11/24

06 Days

7636.41  
 + 140.00  
 + 1990.00  
 -----  
 9766.41

4523.67  
 140  
 1990  
 -----  
 6653.67

- 20% 1953.282  
 -----  
 7813.128

Lump Sum ~~\$7800~~ 6 Days  
 \$5300

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: