



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 48224

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

DATE : 12/11/2024
CLAIM NO. : 12646
POLICY NO. : MC/01009120/03
FROM : RAYMOND

VEHICLE NO. : FBN1744H
MAKE/MODEL : YAM / NMAX155 ABS

*not authorized
in
mechanics
13/11/24
1/5 \$1150
whelp - 4th day
3 days*

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE P/N: 55166 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$13.00	CU7 26.00 ✓
2	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	CU7 37.00 ✓
3	BOARD FOOTREST LH P/N: 59588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$58.00	CU7 58.00 ✓
4	BOX FILTER AIR OUTER P/N: 58141 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	CU7 19.00 ✓
5	BOX FILTER AIR OUTER FRONT P/N: 58164 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	CU7 12.00 ✓
6	BOX REAR (GIVI) E450N SIMPLY II P/N: 80092 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$288.00	CU7 288.00 ✓
7	COVER CLUTCH OUTER P/N: 58147 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	CU7 31.00 ✓
8	COVER CLUTCH OUTER DAMPER 1 P/N: 58111 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	1.11 13.00 ✓
9	COVER CLUTCH OUTER DAMPER 2 P/N: 58172 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	1.11 8.00 ✓

*48224 *



bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	COVER CLUTCH OUTER DAMPER 3 P/N: 58107 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	8.00 <i>nel</i>
11	COVER CLUTCH OUTER DAMPER 4 P/N: 58140 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00 <i>nel</i>
12	COVER SIDE LOWER LH (WHITE) P/N: 58097 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00	24.00 <i>cut</i>
13	COVER SIDE REAR LH (WHITE) P/N: 58170 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$33.00	33.00 <i>cut</i>
14	COWLING FRONT LH (WHITE) P/N: 58179 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$36.00	36.00 <i>cut</i>
15	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00 <i>nel</i>
16	FOOTREST REAR ASSY 1 LH P/N: 58212 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$33.00	33.00 <i>cut</i>
17	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	<i>✱</i> Supply/Install	5.00	\$85.00	425.00 <i>300</i>
18	LAMP SIGNAL FRONT LH P/N: 59587 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$39.00	39.00 <i>one</i>
19	LEVER BRAKE LH P/N: 58145 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00 <i>cut</i>
20	PANEL 1 (MATTE BLACK) LH P/N: 63491 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00	24.00 <i>cut</i>
21	PROTECTOR EXHAUST P/N: 58086 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	42.00 <i>did cut</i> X
22	RIVET P/N: 56583 - (REPORTED BY MECHANIC)	REPLACE	3.00	\$3.00	9.00 <i>nn</i> X
23	Spray lacquer COWLING FRONT LH - SPRAY LACQUER	<i>labour ✱</i> Spray	1.00	\$101.00	101.00 <i>60</i>
24	Spray lacquer COWLING REAR LH - SPRAY LACQUER	<i>labour ✱</i> Spray	1.00	\$70.00	70.00 <i>60</i>

*48224 *



Quotation Nos. : 48224

S/N	Description	Action	Qty	Unit Price	Amount
25	STAND MAIN P/N: 58138 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$72.00	72.00
26	STAND SIDE P/N: 58211 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$26.00	26.00
27	STICKER (CERTIS CISCO) LOGO NEW MODEL LH/RH P/N: 61181 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00	48.00
28	STICKER (CISCO DIAMOND GRADE) BOX REAR P/N: 79322 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
29	STICKER (CISCO DIAMOND GRADE) COWLING FRONT LH P/N: 79323 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	45.00
30	STICKER (CISCO DIAMOND GRADE) COWLING REAR LH P/N: 79321 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
31	STICKER (CISCO DIAMOND GRADE) SIDE BOTTOM COWL LH P/N: 79324 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$57.00	57.00
32	STICKER (CISCO) COWLING FRONT LH P/N: 58616 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
33	STICKER (CISCO) LINING COVER REAR LH P/N: 61573 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
34	TRANSPORT CHARGES P/N: 07169 - ONE WAY TRANSPORT	* Supply/Install	1.00	\$62.00	62.00

SUB TOTAL

\$1,831.00

GST @ 9 %

\$164.79

GRAND TOTAL (SGD)

\$1,995.79

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

*48224

*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Acknowledge & Accepted By

P-809
102
728-10
287
458
14701
282
1176

bizSAFE₃