



QUOTATION

Customer :

NO. : **48224**

- Rev. 1

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

DATE : 12/11/2024
CLAIM NO. : 12646
POLICY NO. : MC/01009120/03

FROM : RAYMOND

VEHICLE NO. : FBN1744H
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE P/N: 55166 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$13.00 Disc %: 10.00	23.40
2	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00 Disc %: 10.00	33.30
3	BOARD FOOTREST LH P/N: 59588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$58.00 Disc %: 10.00	52.20
4	BOX FILTER AIR OUTER P/N: 58141 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00 Disc %: 10.00	17.10
5	BOX FILTER AIR OUTER FRONT P/N: 58164 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
6	BOX REAR (GIVI) E450N SIMPLY II P/N: 80092 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$288.00 Disc %: 10.00	259.20
7	COVER CLUTCH OUTER P/N: 58147 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00 Disc %: 10.00	27.90
8	COVER CLUTCH OUTER DAMPER 1 P/N: 58111 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00 Disc %: 10.00	11.70
9	COVER CLUTCH OUTER DAMPER 2 P/N: 58172 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00 Disc %: 10.00	7.20

*48224 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
10	COVER CLUTCH OUTER DAMPER 3 P/N: 58107 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00 Disc %: 10.00	7.20
11	COVER CLUTCH OUTER DAMPER 4 P/N: 58140 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00 Disc %: 10.00	11.70
12	COVER SIDE LOWER LH (WHITE) P/N: 58097 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00 Disc %: 10.00	21.60
13	COVER SIDE REAR LH (WHITE) P/N: 58170 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$33.00 Disc %: 10.00	29.70
14	COWLING FRONT LH (WHITE) P/N: 58179 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$36.00 Disc %: 10.00	32.40
15	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00 Disc %: 10.00	14.40
16	FOOTREST REAR ASSY 1 LH P/N: 58212 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$33.00 Disc %: 10.00	29.70
17	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	Supply/Install	1.00	\$300.00	300.00
18	LAMP SIGNAL FRONT LH P/N: 59587 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$39.00 Disc %: 10.00	35.10
19	LEVER BRAKE LH P/N: 58145 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00 Disc %: 10.00	17.10
20	PANEL 1 (MATTE BLACK) LH P/N: 63491 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00 Disc %: 10.00	21.60
21	Spray lacquer COWLING FRONT LH - SPRAY LACQUER	Spray	1.00	\$60.00	60.00
22	Spray lacquer COWLING REAR LH - SPRAY LACQUER	Spray	1.00	\$60.00	60.00
23	STAND MAIN P/N: 58138 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$72.00 Disc %: 10.00	64.80
24	STICKER (CERTIS CISCO) LOGO NEW MODEL LH/RH P/N: 61181 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00	48.00

*48224 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
25	STICKER (CISCO DIAMOND GRADE) BOX REAR P/N: 79322 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
26	STICKER (CISCO DIAMOND GRADE) COWLING FRONT LH P/N: 79323 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	45.00
27	STICKER (CISCO DIAMOND GRADE) COWLING REAR LH P/N: 79321 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
28	STICKER (CISCO DIAMOND GRADE) SIDE BOTTOM COWL LH P/N: 79324 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$57.00	57.00
29	STICKER (CISCO) COWLING FRONT LH P/N: 58616 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
30	STICKER (CISCO) LINING COVER REAR LH P/N: 61573 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
31	TRANSPORT CHARGES P/N: 07169 - ONE WAY TRANSPORT	Supply/Install	1.00	\$35.00	35.00

SUB TOTAL	\$1,470.10
GST @ 9 %	\$132.31
GRAND TOTAL (SGD)	\$1,602.41

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

***48224 ***

