

SIN YU SIN WORK HOP

1 KAKI BUKIT AVENUE 6
#01-82 AUTOBAY SINGAPORE 41 383

TO	: INCOME	DA	: 9/12/2024
VEHICLE NO	: SMM7659G	Veron	
VEHICLE MODEL	: TOYOTA PRIUS		
CHASSIS NO	: ZVW506146974		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER Deformed	1	\$ 978.70	\$ 978.70
2	REAR BUMPER SIDE HOLDER Not Rec	2	\$ 127.40	\$ 254.80
3	REAR BUMPER LOWER GARNISH Deformed	1	\$ 565.40	\$ 565.40
4	REAR BUMPER TOW COVER ut	1	\$ 26.90	\$ 26.90
5	REAR BUMPER REINFORCEMENT Dented	1	\$ 568.90	\$ 568.90
6	REAR BUMPER UNDERCOVER Deformed	1	\$ 168.70	\$ 168.70
7	REAR BUMPER LAMP Not Rec	2	\$ 548.90	\$ 1,097.80
8	REAR BUMPER SIDE GARNISH Not Rec	2	\$ 216.50	\$ 433.00
9	REAR BUMPER SENSOR Damaged	2	\$ 201.40	\$ 402.80
10	TAILLAMP Not Rec	2	\$ 557.90	\$ 1,115.80
11	REAR END PANEL Dented	1	\$ 681.40	\$ 681.40
12	REAR END PANEL TOP GARNISH Deformed	1	\$ 290.40	\$ 290.40
13	REAR END PANEL ANTENNA SENSOR cracked	1	\$ 185.30	\$ 185.30
14	TAILGATE	1	\$ 1,538.60	\$ 1,538.60
15	TAILGATE LOCK	1	\$ 457.80	\$ 457.80
16	TAILGATE WEATHERSTRIPE Not Rec	1	\$ 310.40	\$ 310.40
17	TAILGATE OUTER GARNISH	1	\$ 741.40	\$ 741.40
18	TAILGATE INNER TRIM BOARD	1	\$ 511.80	\$ 511.80
19	TAILGATE LOWER GLASS C/W MOULDING Not Rec	1	\$ 486.50	\$ 486.50
20	TAILGATE UPPER GLASS C/W MOULDING Not Rec	1	\$ 1,778.30	\$ 1,778.30
21	TOYOTA LOGO	1	\$ 52.90	\$ 52.90
22	PRIUS WORDING Not Rec	1	\$ 58.70	\$ 58.70
23	HYBRID EMBLEM	1	\$ 69.20	\$ 69.20
24	REAR FENDER INNER TRIM BOARD	2	\$ 612.20	\$ 1,224.40
25	SPARE TYRE PANEL TOP BOARD Not Rec	1	\$ 391.40	\$ 391.40
26	SPARE TYRE PANEL TOP SPONGE Not Rec	2	\$ 398.50	\$ 797.00
27	TOOLS TRAY SPONGE Not Rec	1	\$ 441.30	\$ 441.30

TO AL PRICE: \$ 15,629.60
LES 25% \$ 3,907.40
SU TOTAL PRICE: \$ 11,722.20

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE Not Rec	1	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE HOLDER Not Rec	1	\$ 30.00	\$ 30.00
3	REAR BUMPER CLIPS (SET) Not Rec	1	\$ 30.00	\$ 30.00
4	REAR BUMPER UNDERCOVER CLIPS (SET) Not Rec	1	\$ 20.00	\$ 20.00
5	REAR END PANEL SEALANT Not Rec	1	\$ 60.00	\$ 60.00
6	REAR END PANEL TOP GARNISH CLIPS (SET) Not Rec	1	\$ 20.00	\$ 20.00

7	TAILGATE OUTER GARNISH CLIPS (SET)	1	\$ 30.00	\$ 30.00	+
8	TAILGATE INNER TRIM BOARD CLIPS (SET)	1	\$ 30.00	\$ 30.00	+
9	TAILGATE LOWER GLASS SEALANT	1	\$ 100.00	\$ 100.00	+
10	TAILGATE UPPER GLASS SEALANT	1	\$ 100.00	\$ 100.00	+
11	REAR FENDER INNER TRIM BOARD CLIP (SET)	2	\$ 30.00	\$ 60.00	+
TOTAL :				\$ 510.00	

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,400.00	600	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	400	
3	WIRING CHECK	\$ 50.00	30	
4	TO REMOVE REAR BUMPER SENSOR	\$ 100.00	50	
5	TO REMOVE UPHOLSTERY	\$ 150.00	60	
6	TO APPLY TUFF COAT	\$ 150.00	60	
7	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	x	
8	TO REMOVE TAILGATE LOWER GLASS	\$ 150.00	+	
9	TO REMOVE TAILGATE UPPER GLASS	\$ 180.00	+	
TOTAL:		\$ 5,530.00		

ESTIMATE REPORT

TOTAL PARTS COST: \$ 12,232.20

TOTAL LABOUR COST: \$ 3,530.00

TOTAL REPAIR COST: \$ 15,762.20

total: 4231.37

2/5: 3.3k ✓
04 Days.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: