

VIN'S

Estimated Cost of Repair

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : OD/112024/7832
Date : 07-11-2024
Accident Date : 06-11-2024

Vehicle Details

Make & Model : Audi A4 1.8 TFSI MU
Chassis No : WAUZZZ8K6BA058471
Registration No : SNM492D

Not Notified
L1 Pump &
Pressure After Pump
6 days
Ex @ 1250.

S/N	Description	Qty	Amount (S\$)	
1	FRONT BONNET	1.00	<i>Br</i> \$1,600.00	✓
2	BONNET RH HINGE	1.00	<i>Di's</i> \$50.00	✓
3	BONNET LH HINGE	1.00	<i>Di's</i> \$50.00	✓
4	BONNET LOCK	1.00	\$130.00	?
5	FRONT GRILLE ASSY	1.00	<i>Br</i> \$550.00	✓
6	RH HEADLAMP	1.00	<i>mgm</i> \$1,100.00	✓
7	LH HEADLAMP	1.00	<i>Br</i> \$1,100.00	✓
8	RH HEADLAMP LOWER BRACKET	1.00	<i>CM</i> \$80.00	✓
9	LH HEADLAMP LOWER BRACKET	1.00	<i>CM</i> \$80.00	✓
10	FRONT BUMPER	1.00	<i>CM</i> \$1,300.00	✓
11	FRONT BUMPER LH FOG LAMP	1.00	\$140.00	?
12	FRONT BUMPER LH FOG LAMP COVER	1.00	<i>mi's</i> \$110.00	✓
13	FRONT BUMPER RH FOG LAMP COVER	1.00	<i>Br</i> \$110.00	X
14	FRONT BUMPER TOWING COVER	1.00	<i>Br</i> \$40.00	X
15	FRONT BUMPER RH SIDE RETAINER	1.00	<i>Di's</i> \$40.00	✓
16	FRONT BUMPER LH SIDE RETAINER	1.00	<i>Di's</i> \$40.00	✓
17	FRONT BUMPER SPONGE	1.00	<i>CM</i> \$70.00	✓
18	FRONT BUMPER REINFORCEMENT	1.00	<i>Br</i> \$520.00	✓
19	FRONT BUMPER UNDER COVER	1.00	\$110.00	?
20	FRONT BUMPER CLIPS	10.00	<i>Br</i> \$20.00	✓
21	FRONT SUPPORT PANEL	1.00	<i>CM</i> \$520.00	✓
22	FRONT SUPPORT TOP COVER	1.00	<i>Br</i> \$90.00	✓
23	FRONT SUPPORT TOP COVER CLIPS	10.00	<i>Br</i> \$20.00	✓
24	BRACE PANEL (14)	1.00	\$40.00	?
25	AIRCON CONDENSER	1.00	<i>Br</i> \$550.00	✓
26	AIRCON CONDENSER FAN MOTOR	1.00	\$380.00	?
27	RADIATOR	1.00	<i>hous cm</i> \$520.00	✓
28	RADIATOR FAN MOTOR	1.00	\$380.00	?
29	RADIATOR FAN COWLING	1.00	<i>CM</i> \$160.00	✓
30	INTERCOOLER	1.00	<i>Br</i> \$490.00	✓



VIN S

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

IMPORT
1. Please
2. This f
3. Inform
policy li
4. The
5. Any
6. This
and th
7. By

31	FRONT LH FENDER	1.00	Bn	\$580.00	✓
32	FRONT RH FENDER	1.00	Bn	\$580.00	✓
				\$11,550.00	
33	FRONT NO. PLATE	1.00	mt	\$40.00	✓
34	COOLANT	1.00	Na	\$80.00	401n
35	TO REFILL AIRCON GAS	1.00		\$150.00	100l
36	TO RESET HEADLAMP SYSTEM	1.00		\$280.00	20l
37	TO REPAIR DAMAGES	1.00		\$919.80	600l
38	TO SPRAY PAINTING	1.00		\$940.80	800l

Subtotal w/o GST: \$13,960.60

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Mohamad Hakim Bin Anuar

This is a computer-generated document. No signature is required.