

ASS. REC. BY:

REF:

C72/ CS/ CT1 24110250/ Kbh3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

JNM 4920

Yr Regn:

01, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4

c.c

1790

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

21 4213

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAT 888 PK 88 A 058471

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

Rear

R/Bal.

7

mm

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

6/11/24

D.O.I.

13/11/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Modify for brake caliper.

28/11 11:00 am 7300 Car (Red, \$6600.00, 47%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees:

Others:

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Estimated Cost of Repair

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : OD/112024/7832
Date : 07-11-2024
Accident Date : 06-11-2024

Vehicle Details

Make & Model : Audi A4 1.8 TFSI MU
Chassis No : WAUZZZ8K6BA058471
Registration No : SNM492D

Not Notified
L1 Imp & 7300h Max
Recovery After Paim
6 days
Ex \$1250.

S/N	Description	Qty	Amount (\$\$)	
1	FRONT BONNET	1.00	Bn \$1,600.00	✓
2	BONNET RH HINGE	1.00	Dij \$50.00	✓
3	BONNET LH HINGE	1.00	Dij \$50.00	✓
4	BONNET LOCK	1.00	R \$130.00	✓
5	FRONT GRILLE ASSY	1.00	Bn \$550.00	✓
6	RH HEADLAMP	1.00	Mgcm \$1,100.00	✓
7	LH HEADLAMP	1.00	Bn \$1,100.00	✓
8	RH HEADLAMP LOWER BRACKET	1.00	CMA \$80.00	✓
9	LH HEADLAMP LOWER BRACKET	1.00	CMA \$80.00	✓
10	FRONT BUMPER	1.00	CMA \$1,300.00	✓
11	FRONT BUMPER LH FOG LAMP	1.00	Sn \$140.00	✓
12	FRONT BUMPER LH FOG LAMP COVER	1.00	Mij \$110.00	✓
13	FRONT BUMPER RH FOG LAMP COVER	1.00	Sn \$110.00	X
14	FRONT BUMPER TOWING COVER	1.00	Rn \$40.00	X
15	FRONT BUMPER RH SIDE RETAINER	1.00	Dij \$40.00	✓
16	FRONT BUMPER LH SIDE RETAINER	1.00	Dij \$40.00	✓
17	FRONT BUMPER SPONGE	1.00	CMA \$70.00	✓
18	FRONT BUMPER REINFORCEMENT	1.00	Bn \$520.00	✓
19	FRONT BUMPER UNDER COVER	1.00	Sn \$110.00	✓
20	FRONT BUMPER CLIPS	10.00	Mn \$20.00	✓
21	FRONT SUPPORT PANEL	1.00	CMA \$520.00	✓
22	FRONT SUPPORT TOP COVER	1.00	Bn \$90.00	✓
23	FRONT SUPPORT TOP COVER CLIPS	10.00	Mn \$20.00	✓
24	BRACE PANEL (14)	1.00	R \$40.00	✓
25	AIRCON CONDENSER	1.00	Pn \$550.00	✓
26	AIRCON CONDENSER FAN MOTOR	1.00	Sn \$380.00	✓
27	RADIATOR	1.00	hous cm \$520.00	✓
28	RADIATOR FAN MOTOR	1.00	Sn \$380.00	✓
29	RADIATOR FAN COWLING	1.00	CMA \$160.00	✓
30	INTERCOOLER	1.00	Bn \$490.00	✓

VIN'S

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

31	FRONT LH FENDER	1.00	Bn	\$580.00	✓
32	FRONT RH FENDER	1.00	Bn	\$580.00	✓
				\$11,550.00	
33	FRONT NO. PLATE	1.00	Mr	\$40.00	✓
34	COOLANT	1.00	Mr	\$80.00	400ml
35	TO REFILL AIRCON GAS	1.00		\$150.00	1000l
36	TO RESET HEADLAMP SYSTEM	1.00		\$280.00	20l
37	TO REPAIR DAMAGES	1.00		\$919.80	600l
38	TO SPRAY PAINTING	1.00		\$940.80	800l

Subtotal w/o GST: \$13,960.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Issued by Mohamad Hakim Bin Anuar

This is a computer-generated document. No signature is required.