



Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
 (Singapore) Pte Ltd
 3 Anson Road
 #15-00 Springleaf Tower
 Singapore 079909

Claim Details

Case Ref. No. : OD/112024/7832
 Date : 07-11-2024
 Accident Date : 06-11-2024

Vehicle Details

Make & Model : Audi A4 1.8 TFSI MU
 Chassis No : WAUZZZ8K6BA058471
 Registration No : SNM492D

Not Notified
L1 Rep & 7300h Max
Recovery After Claim
6 days Ex @ 1250.

S/N	Description	Qty	Amount (S\$)	
		1.00	<i>By</i> \$1,600.00	✓
1	FRONT BONNET	1.00	<i>Di's</i> \$50.00	✓
2	BONNET RH HINGE	1.00	<i>Di's</i> \$50.00	✓
3	BONNET LH HINGE	1.00	<i>R</i> \$130.00	✓
4	BONNET LOCK	1.00	<i>Bo</i> \$550.00	✓
5	FRONT GRILLE ASSY	1.00	<i>Mjcm</i> \$1,100.00	✓
6	RH HEADLAMP	1.00	<i>Bo</i> \$1,100.00	✓
7	LH HEADLAMP	1.00	<i>CM</i> \$80.00	✓
8	RH HEADLAMP LOWER BRACKET	1.00	<i>CM</i> \$80.00	✓
9	LH HEADLAMP LOWER BRACKET	1.00	<i>CM</i> \$1,300.00	✓
10	FRONT BUMPER	1.00	<i>Sn</i> \$140.00	✓
11	FRONT BUMPER LH FOG LAMP	1.00	<i>Mi's</i> \$110.00	✓
12	FRONT BUMPER LH FOG LAMP COVER	1.00	<i>Sn</i> \$110.00	X
13	FRONT BUMPER RH FOG LAMP COVER	1.00	<i>Sn</i> \$40.00	X
14	FRONT BUMPER TOWING COVER	1.00	<i>Di's</i> \$40.00	✓
15	FRONT BUMPER RH SIDE RETAINER	1.00	<i>Di's</i> \$40.00	✓
16	FRONT BUMPER LH SIDE RETAINER	1.00	<i>CM</i> \$70.00	✓
17	FRONT BUMPER SPONGE	1.00	<i>Bo</i> \$520.00	✓
18	FRONT BUMPER REINFORCEMENT	1.00	<i>Sn</i> \$110.00	✓
19	FRONT BUMPER UNDER COVER	10.00	<i>Ma</i> \$20.00	✓
20	FRONT BUMPER CLIPS	1.00	<i>CM</i> \$520.00	✓
21	FRONT SUPPORT PANEL	1.00	<i>Bo</i> \$90.00	✓
22	FRONT SUPPORT TOP COVER	10.00	<i>Ma</i> \$20.00	✓
23	FRONT SUPPORT TOP COVER CLIPS	1.00	<i>R</i> \$40.00	✓
24	BRACE PANEL (14)	1.00	<i>Pu</i> \$550.00	✓
25	AIRCON CONDENSER	1.00	<i>Sn</i> \$380.00	✓
26	AIRCON CONDENSER FAN MOTOR	1.00	<i>hours cont</i> \$520.00	✓
27	RADIATOR	1.00	<i>Sn</i> \$380.00	X
28	RADIATOR FAN MOTOR	1.00	<i>CM</i> \$160.00	✓
29	RADIATOR FAN COWLING	1.00	<i>Bo</i> \$490.00	✓
30	INTERCOOLER			



Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

31 FRONT LH FENDER
 32 FRONT RH FENDER

1.00 *Bu* \$580.00 ✓
 1.00 *Bn* \$580.00 ✓

33 FRONT NO.PLATE
 34 COOLANT
 35 TO REFILL AIRCON GAS
 36 TO RESET HEADLAMP SYSTEM
 37 TO REPAIR DAMAGES
 38 TO SPRAY PAINTING

\$11,550.00
 1.00 *mit* \$40.00 ✓
 1.00 *na* \$80.00 *40sn*
 1.00 \$150.00 *100l*
 1.00 \$280.00 *20l*
 1.00 \$919.80 *600l*
 1.00 \$940.80 *800l*

Subtotal w/o GST: \$13,960.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Issued by Mohamad Hakim Bin Anuar

This is a computer-generated document. No signature is required.