



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP(NTUC) *LONPAC*Vehicle No. : SML5488BMake & Model : TOYOTA PRIUSYear of Manufacture : 2018Chassis No. : JTDKB3FU003081000Engine No. : 2ZR2C22914

Policy No. : _____

Time of Accident : _____

Ins Company : III

Excess : _____

Date of Accident : 3/11/2024

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair EstimatesCase Owner : KELVIN

Signature : _____

Parts (a) Cost / List Price Items \$ 3,665.00Plus/Less 25% \$ 916.25Total of Cost / List \$ 2,748.75

(b) Nett Price Items _____

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 2,748.75Labour (Appendix B) \$ 1,670.00Total Repair Cost \$ 4,418.75**Operation**

KELVIN SU

TEL: 9786 4236

E: kelvinsukwen@cdge.com.sg

SUN PIN

TEL: 9728 8916

E: oisunpin@cdge.com.sg

The above total will be subjected to 9% G.S.T.

Name of Surveyor : Kenneth
 Company : CKK
 Survey conducted on : 13/11/24 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : De Date: 13/11/24

*Not authorized
 11pm @ 1900h
 Penny After King*

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SML5488B Case Owner : KELVIN

Make & Model : TOYOTA PRIUS Year Manufacture : 2018

Chassis No : JTDKB3FU003081000 Engine No : 2ZR2C22914

Sales Order : _____ Supplier : _____

Order By : KELVIN Type of Claim : TP(NTUC)

S/No	DESCRIPTION	QTY	Cost Price	List Price	S/N	Disposition By Surveyor
1	LHR DOOR	1	<i>R</i>	\$ 1,900.00		✓
2	LHR DOOR FRAME STICKER	1	<i>M</i>	\$ 210.00		✓
3	LHR FENDER	1	<i>R</i>	\$ 1,500.00		X
4	FENDER COWLING CLIPS	10	<i>~</i>	\$ 55.00		X
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No. : SML5488B
Make & Model : TOYOTA PRIUS

Case Owner	:	<u>KELVIN</u>
Year of Manufacture	:	<u>2018</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.