

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Vehicle No.

SML5488B

Our Ref:

Type of Claim T	P(NTUC)	venicie ivo.	8 9	3WL3400D
	,	Make & Model	£ .	TOYOTA PRIUS
		Year of Manufacture		2018
		Chassis No.	1	JTDKB3FU003081000
Ins Company	iii .	Engine No.	2	2ZR2C22914
Excess		Policy No.	20	
Date of Accident 3	/11/2024	Time of Accident	ř.	
Suggested Days of Repair 🖁 📜		In-house Vehicle Asse	ssor	
Repair Estimates		Case Owner	ii o	KELVIN
Parts (a) Cost / List Price Items	\$ 3,665.00	Signature	Ð 0	
Plus/Less 25%	\$ 916.25			
	=======================================			
Total of Cost / List	\$ 2,748.75	Operation KELVIN SU		
(b) Nett Price Items		TEL: 9786 4236	S-4-	ran randonato nantari
Less		E: kelvinsukwen@	<u>v</u> coq	e.com.sg
Total of Nett Item		SUN PIN TEL: 9728 8916		
(c) Special Nett Items	\$	E: oisunpin@cdg	e.cor	m.sg
Total Parts Cost (Appendix A)	\$ 2,748.75			
Labour (Appendix B)	\$ 1,670.00			
Total Repair Cost	\$ 4,418.75			
The above total will be subjected	to 9% G.S.T.			
Name of O	<u>.</u>			
Name of Surveyor Company				
Survey conducted on	* <u></u>	at		
Survey contactor on	· -			
Remarks By Surveyor				
(a) The repair of this vehicle is	s authorized / is not aut	horized until further notice	e.	
(b) Recommended Days of R	epair :	day(s)		
(c) Resurvey	Required / No	t Required		
(d) Excess	:\$			
(e) Signature of surveyor	ű <u>-</u>	Date	:	
VACCIDENT REPAIR ESTIMATES/E3				

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No	SML5488B	Case Owner:	KELVIN
Make & Model	: TOYOTA PRIUS	Year Manufacture:	2018
Chassis No	: <u>JTDKB3FU003081000</u>	Engine No :	2ZR2C22914
Sales Order	ž	Supplier :	-
Order By	: KELVIN	Type of Claim:	TP(NTUC)

S/No	DESCRIPTION	QTY	Cost	List	621	Disposition By
1	LHR DOOR		Price	Price	S/N	Surveyor
		1		\$ 1,900.00		+
	LHR DOOR FRAME STICKER	1		\$ 210.00		
-	LHR FENDER	1		\$ 1,500.00		
	FENDER COWLING CLIPS	10		\$ 55.00		
5				1		
6						
7						
8						
10				+		
11				+		
12						
13				1	_	
14				+		
15						
16				1		-
17						
18						
19						1
20						
21						
22						
23						
24						
25						
26						-
27	-					1
28						
29						
30						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax: 62815767

Labour

Vehicle No. :	SML5488B	Case Owner	: _	KELVIN
Make & Model:	TOYOTA PRIUS	Year of Manufacture	:	2018

	Teal of Mandiacture			
S/No	Labour Description	Esimated Price	Adjusted Price	
1_	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA, TO REMOVE &	\$ 750.00		
	REFIT DAMAGE PARTS			
2	TO PUTTY,RESPRAY ON LHR DOOR,LHR FENDER	\$ 750.00		
	AFFECTED AREA			
3	TO REMOVE/REFIT REAR WINDSCREEN	\$ 120.00		
4	TO TUFF COAT/WATER PROOFING	\$ 50.00		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.