

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24110252/KMA3Q2**Date:** 10/02/2026REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7220111540  
**Claimant Vehicle No :** SLU9139Y **Insured Vehicle No :** SMF1195D  
 Date of Loss: 11/11/2024 Nature of Claim: TP Claim No: 3526349758SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU9139Y**  
 Make & Model: TOYOTA HARRIER, 2.0 PREMIUM CVT (A) Engine No: 3ZRB996060  
 Reg. Date: 18/12/2017 (Man. Year: 2017) Chassis No: ZSU600104563  
 Colour: Metallic Dark Blue Odometer: 177042 km  
 Engine Capacity: 1986 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18  
 Front Left Side: Goodyear 3 mm Rear Left Side: Yokohama 5 mm  
 Front Right Side: Goodyear 3 mm Rear Right Side: Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,352.35	4,283.57	68.78	1.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,470.00	1,060.00	410.00	27.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,822.35</b>	<b>5,343.57</b>	<b>478.78</b>	<b>8.22</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,250.00</b>		
<b>(S\$)</b>	5,822.35	4,250.00	1,572.35	27.01
<b>+ GST 9.00/9.00% (S\$)</b>	524.01	382.50	141.51	27.01
<b>Nett Amount (S\$)</b>	<b>6,346.36</b>	<b>4,632.50</b>	<b>1,713.86</b>	<b>27.01</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		2.18		
<b>Nett Liability (S\$)</b>		<b>5,034.68</b>		

INSPECTION

Date of Assignment: 18/11/2024  
 Date Inspected: 18/11/2024 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)  
 BLK 1019 #01-374/382, Yishun Industrial Park A  
 Singapore 768761  
 Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	2,236.30 FL	*2,236.30 FL
2	1		*REAR BUMPER LOWER SKIRT COVER	Dented / Cut	649.40 FL	*649.40 FL
3	6		*REAR BUMPER CLIP	Necessary	33.00 FL	*33.00 FL
4	1		*REAR TAILGATE	Bent	2,427.00 FL	*2,427.00 FL
5	1		*TAILGATE EMBLEM HARRIER	Necessary	91.80 FL	*91.80 FL
6	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	220.60 FL	*220.60 FL
7	1		*REAR SMART KEY SENSOR	Serviceable	91.70 FL	*- FL
8	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,789.80</b>	<b>5,698.10</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	1,437.45	1,414.53
<b>Total Parts (\$)</b>	<b>4,352.35</b>	<b>4,283.57</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY TAILGATE & ATTACHMENTS TO KNOCKING & REPAIR REAR PANEL & REALIGN THE SAME	New	600.00	450.00
3	PUTTY & RESPRAY ON REAR BUMPER ,TAILGATE ,REAR PANEL & REAR AFFECTED AREAS	New	700.00	440.00
4	REMOVE & REFIX REVERSE CAMERA SENSOR & SMART KEY SENSOR & RESET SYSTEM	New	50.00	50.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,470.00</b>
				<b>1,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >