

Not Withstand
 L1 Sm & 4450p
 Recovery After Paint
 5 days

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : SMQ 9930M

S/N	Parts Description	Unit Price	Amt
1	Rear tailgate ✓	\$1,177.00	By \$1,177 ✓
2	Rear tailgate emlem	\$68.00	nn \$68.00 X
3	Rear tailgate DSI emblem ✓	\$72.10	nn \$72.10 —
4	Rera tailgate X emblem ✓	\$58.00	nn \$58.00 —
5	Rear tailgate outer garnish	\$371.25	nn \$371.25 X
6	Rear tailgate lock	\$360.00	R \$360.00 X
7	Rear tailgate rubber ✓	1605N Dis 10d \$320.00	\$320.00 508nn
8	Rear tailgate inner board X not damaged	\$499.80	ngcm \$499.80 — X
9	Rear tailgate windscreen mldg ✓	\$151.60	nn \$151.60 —
9	Rear bumper ✓	Bu \$823.00	\$823.00 —
10	Rear bumper retainer X 2	NLS cm \$132.45	\$264.90 —
11	Rear bumper inner bracket LH	\$132	R \$132 X
12	Rear bumper reflector X 2	NLS ngcm \$76.80	\$153.60 —
13	Taillamp LH & RH	NLS cm \$667.70	\$1,335.40 —
14	Rear end panel ✓	\$687.30	By \$687.30 —
15	Rear end panel top garnish ✓	ng d11 \$255.80	\$255.80 —
16	Rear tool box ✓	251 \$601.40	cm \$601.40 —
Special Nett			
1	Rear bumper clips ✓	\$50.00	nn \$50.00 —
2	Rear No. plate	\$60.00	nn \$60.00 X
3	Rear windscreen sealant ✓	\$80.00	nn \$80.00 408nn
4	Rear bumper reverse sensor	\$285.00	NLP \$285.00 X

Labour

1	To remove and refit damaged parts, cut/weld damaged areas. ✓	\$1000.00	60d
2	To spray paint on affected areas. ✓	\$1,000.00	60d
3	To remove and refit rear windscreen ✓	\$200.00	12d
4	To remove and refit reverse sensor ✓	\$100.00	5d
5	Check wiring ✓	\$50.00	2d
6	Tuff coating ✓	\$120.00	6d

\$2,470.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: