

ASS. REC. BY:

REF: LIP/ CS/LIP24110255/Kvh3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s THHof 849CInsured: SGQ 8850M

Policy No. _____

Claims No. IVS24/2112

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 892K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMQ 9930M Tr Regn: 12, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Prius C.C. 1797Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 436510 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZVW40 0032204

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 9/11/24 D.O.I. 12/11/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/11 LIP 849501 Colur (red 5826.15, 56%)

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trlp: _____

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Transportation

S + RS. SI

Fees

Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Not Authorized
 L1Pm @ 4450h
 Recovery After Paint
 5 days

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : SMQ 9930M

S/N	Parts Description	Unit Price	Amt	
		\$1,177.00	Ry	\$1,177 ✓
1	Rear tailgate	\$68.00	nn	\$68.00 X
2	Rear tailgate emlem	\$72.10	nn	\$72.10 —
3	Rear tailgate DSI emblem	\$58.00	nn	\$58.00 —
4	Rera tailgate X emblem	\$371.25	ln	\$371.25 X
5	Rear tailgate outer garnish	\$360.00	R	\$360.00 X
6	Rear tailgate lock	\$320.00		\$320.00 502sn
7	Rear tailgate rubber	\$499.80	mycm	\$499.80 —
8	Rear tailgate inner board	\$151.60	nn	\$151.60 —
9	Rear tailgate windscreen mldg	\$823.00	Bu	\$823.00 —
9	Rear bumper	\$132.45	NLS cm	\$264.90 —
10	Rear bumper retainer X 2	\$132	R	\$132 X
11	Rear bumper inner bracket LH	\$76.80	NLS mycm	\$153.60 —
12	Rear bumper reflector X 2	\$667.70	NLS cm	\$1,335.40 —
13	Taillamp LH & RH	\$687.30	Ry	\$687.30 —
14	Rear end panel	\$255.80	my DIT	\$255.80 —
15	Rear end panel top garnish	\$601.40	cm	\$601.40 —
16	Rear tool box			
	Special Nett	\$50.00	nn	\$50.00 —
1	Rear bumper clips	\$60.00	sn	\$60.00 X
2	Rear No. plate	\$80.00	nn	\$80.00 40sn
3	Rear windscreen sealant	\$285.00	NLS	\$285.00 X
4	Rear bumper reverse sensor			

Labour

1 To remove and refit damaged parts, cut/weld damaged areas.	\$1000.00	60d
2 To spray paint on affected areas.	\$1,000.00	60d
3 To remove and refit rear windscreen	\$200.00	12d
4 To remove and refit reverse sensor	\$100.00	5d
5 Check wiring	\$50.00	2d
6 Tuff coating	\$120.00	6d

\$2,470.00

10,276.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: