

Not Withheld
 L1 Sm @ 4450p
 Return After Paint
 5 days

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : SMQ 9930M

S/N	Parts Description	Unit Price	Amt
1	Rear tailgate	\$1,177.00	By \$1,177 ✓
2	Rear tailgate emlem	\$68.00	nn \$68.00 X
3	Rear tailgate DSI emblem	\$72.10	nn \$72.10 —
4	Rera tailgate X emblem	\$58.00	nn \$58.00 —
5	Rear tailgate outer garnish	\$371.25	nn \$371.25 X
6	Rear tailgate lock	\$360.00	R \$360.00 X
7	Rear tailgate rubber	\$320.00	1605N Dis 10d \$320.00 508nn
8	Rear tailgate inner board	\$499.80	ngcm \$499.80 —
9	Rear tailgate windscreen mldg	\$151.60	nn \$151.60 —
9	Rear bumper	\$823.00	Bu \$823.00 —
10	Rear bumper retainer X 2	\$132.45	NLS cm \$264.90 LT
11	Rear bumper inner bracket LH	\$132	R \$132 X
12	Rear bumper reflector X 2	\$76.80	NLS ngcm \$153.60 LT
13	Taillamp LH & RH	\$667.70	NLS cm \$1,335.40 LT
14	Rear end panel	\$687.30	By \$687.30 —
15	Rear end panel top garnish	\$255.80	ngdiy \$255.80 —
16	Rear tool box	\$601.40	cm \$601.40 —
Special Nett			
1	Rear bumper clips	\$50.00	nn \$50.00 —
2	Rear No. plate	\$60.00	nn \$60.00 X
3	Rear windscreen sealant	\$80.00	nn \$80.00 405N
4	Rear bumper reverse sensor	\$285.00	NLP \$285.00 X

Labour

1	To remove and refit damaged parts, cut/weld damaged areas.	\$1000.00	60d
2	To spray paint on affected areas.	\$1,000.00	60d
3	To remove and refit rear windscreen	\$200.00	12d
4	To remove and refit reverse sensor	\$100.00	5d
5	Check wiring	\$50.00	2d
6	Tuff coating	\$120.00	6d

\$2,470.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: