IMPERIUM AUTOMOTIVE

13/11/24

25 Kaki Bukit Road 4 # 01-47 Synergy@KB, Singapore 417800

HP: 9748 9940 Shawn Tan

Email: shawn7530@hotmail.com

13 NOVEMBER 2024

Vehicle No: SKU8831A		Model : TO	lodel : TOYOTA COROLLA ALTIS		
QTY	<u>List Items</u>			AMOUNT	
1	Rear Windscreen Moulding		11	\$128.80 🗴	
1	Rear Boot Lid	30	مرم کم	\$1132.70	
2	Rear Boot Hinges		su	\$171.40	
2	Rear Boot Lamps		Che	\$850.60	
1	Rear Boot Lock		1wi	\$247.20	
1	Rear Boot Rubber		Twi	\$145.70	
1	Rear Boot "COROLLA" Emblem		nu	\$80.30	
1	Rear Boot "ALTIS" Emblem		ner	\$75.70 /	
2	Rear Tail Lamps		cna	\$1011.20	
1	Rear End Panel		50	\$777.40	
1	Rear End Panel Inner Garnish		401	\$200.30	
	Rear Keyless Sensor		Dange	\$185.20	
1	Rear Bumper		013	\$723.10 —	
1 2	Rear Bumper Top Brackets		cn	\$181.80	
2	Rear Bumper Side Brackets		11	\$97.00 X	
	Rear Bumper Reflector		11	\$120.20 X	
2	Rear Bumper Reinforcements		9	\$469.10	
1	Rear Bumper Reinforcements stays		11	\$161.00 💢	
2			v1		
2	Rear Bumper Side Retainers	+5:10	116.400	\$571.80 17 C	
2	1100.		and Alm	\$571.80 (PC \$363.50 \$1100.70	
1	Rear Spare Tyre Board		001/201/201	\$1100.70 🐰	
1	Rear Spare Tyre Panel				

1	Rear Exhaust Silencer		11	\$881.70 〉		
2	Rear Exhaust Mountings		11	\$97.20 <sub>X</sub>		
2	Rear finder Inner Trims 338.40	NISA	1 0/17000	\$670.80 PC		
2	Rear Fender		R	\$1687.60 X		
2	Rear Tail Lamps Panel		R	\$462.40 X		
		Less 25%		<b>\$12,724.40</b> \$3181.10		
				\$9543.30		
	Special Nett Items					
1	Rear Bumper Clips (1 set)		nec	\$50.00 30 5/2		
1	Rear Number Plate with Holder		SIL	\$50.00 30 5/N \$50.00 40 5/N		
1	Rear Reverse Camera			\$480.00 X		
1	Rear Windscreen Sealant		NA	\$80.00 🗴		
			Marrian or so considerate and	\$660.00		
	Lahaus Charres					
Labour Charges						
To Remove, Replaced damaged lamps and check up rear wiring				\$80.00 W		
To Remove & Refit Inner Garnishes				\$180.00 6 g \$150.00 3 g		
To Remove & Refit Rear Reverse Sensor				\$150.00 50		
To Transfer boot lid mechanism and wiring assembly				\$120.00 X		
To Remove, Refit and replace exhaust silencer and mountings  To Remove & Refit Rear Windscreen Glass				\$180.00 X		
				\$180.00 60		
To Apply Undercoating  Panel Beating				\$2000.00 900		
To Respray painting on the affected areas				\$1800.00		
10 Kespiay p	LKK Auto Consultants hence notify					
	the Repairer of the following:  To recurvey before/after spray pointing:  To display decreased part in the recurrence of the part of the recurrence of the r			\$4840.00		
	To display damaged part(u) in the recurroy Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" bacts No illegal modification(s) is allowed	Grand	Total	\$15,043.30 P- 702430 252 5-U&-23		
	Supplementary item(s) must be resurveyed en.!     is subject to final approval from Insurance Company			70		

Acknowledged by Repairer

Signature:

70 7558-17