

(08/11/13) Wf f

ASS. REC. BY: Marcus

REF:

CS/INC 24/10257/Unh3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKU8831A

at Workshop m/s

Ingrum

of _____

Insured: _____

SDR 20885

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

820k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

7

days

Res.: Yes or No

Lum Sum: _____

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

CS-33e
Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No:

SKU8831A

Yr Regn:

14/07/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Toyota Corolla Altis

c.c.

1598

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

126823

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

MR 053REH 104535977

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/11/24

D.O.I.

13/11/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction Dep 14K

20/11/24
 13-07-2025 FTA & 13707 Bal 8mth. NR4 862P
 1/5 \$ 6000 - 1/5 shown 19-11-24 present.
 (Red. \$ 9043.30, 60%)

Date/Time, File Pass to?



Preli. Report

Days Of Repair: 7

1)



Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:



Site Insp (\$

)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 # 01-47 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan

Email : shawn7530@hotmail.com

not Authorized
do
not
13/11/24

7 days 1/5 \$ 6000

Whe pte. Attorney

13 NOVEMBER 2024

Vehicle No: SKU8831A

Model : TOYOTA COROLLA ALTIS

QTY	List Items	AMOUNT
1	Rear Windscreen Moulding	11 \$128.80 X
1	Rear Boot Lid	body 22 \$1132.70 ✓
2	Rear Boot Hinges	SC \$171.40 X
2	Rear Boot Lamps	CN \$850.60 ✓
1	Rear Boot Lock	1w1 \$247.20 ✓
1	Rear Boot Rubber	1w1 \$145.70 ✓
1	Rear Boot "COROLLA" Emblem	1w1 \$80.30 ✓
1	Rear Boot "ALTIS" Emblem	1w1 \$75.70 ✓
2	Rear Tail Lamps	CN \$1011.20 ✓
1	Rear End Panel	22 \$777.40 ✓
1	Rear End Panel Inner Garnish	1w1 \$200.30 ✓
1	Rear Keyless Sensor	Dange \$185.20 ✓
1	Rear Bumper	213 \$723.10 ✓
2	Rear Bumper Top Brackets	CN \$181.80 ✓
2	Rear Bumper Side Brackets	11 \$97.00 X
2	Rear Bumper Reflector	11 \$120.20 X
1	Rear Bumper Reinforcements	22 \$469.10 ✓
2	Rear Bumper Reinforcements stays	11 \$161.00 X
2	Rear Bumper Side Retainers	11 \$130.00 X
2	Rear Bumper PDC Sensors	245.10 not authorized \$571.80 1P C
1	Rear Spare Tyre Board	weq ad / 701- \$363.50 ✓
1	Rear Spare Tyre Panel	R \$1100.70 X

1	Rear Exhaust Silencer	11	\$881.70 X
2	Rear Exhaust Mountings	11	\$97.20 X
2	Rear fender Inner Trims 335-40	n/s 11 o/s 7011	\$670.80 PC
2	Rear Fender		\$1687.60 X
2	Rear Tail Lamps Panel	R	\$462.40 X
			<hr/>
			\$12,724.40
Less 25%			\$3181.10
			<hr/>
			\$9543.30

Special Nett Items

1	Rear Bumper Clips (1 set)	1cc	\$50.00 30 S/W
1	Rear Number Plate with Holder	SCR	\$50.00 40 S/W
1	Rear Reverse Camera	su	\$480.00 X
1	Rear Windscreen Sealant	11	\$80.00 X
			<hr/>
			\$660.00

Labour Charges

To Remove, Replaced damaged lamps and check up rear wiring	\$80.00 20
To Remove & Refit Inner Garnishes	\$180.00 60
To Remove & Refit Rear Reverse Sensor	\$150.00 30
To Transfer boot lid mechanism and wiring assembly	\$120.00 50
To Remove, Refit and replace exhaust silencer and mountings	11 \$150.00 X
To Remove & Refit Rear Windscreen Glass	11 \$180.00 X
To Apply Undercoating	\$180.00 60
Panel Beating	\$2000.00 900
To Respray painting on the affected areas	\$1800.00 1100

Grand Total \$15,043.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 702430
252
5268.23
70
2220
7558.23