



DICKSON GROUP
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

QUOTATION

QUOTATION FOR

DATE: 13/11/2024

NAME: India International Insurance Pte Ltd
COMPANY NAME: India International Insurance Pte Ltd
STREET ADDRESS: 64 Cecil Street, #04/#05-02, IOB Building
POSTAL CODE: Singapore 049711
PHONE: 6347 6100

REF: SD0B24BC0001
VEHICLE NO: SLH8844U
MAKE: TOYOTA
MODEL: VELLFIRE
PREPARED BY: XIANG

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
LABOUR							
1	TO REMOVE & REPLACE BUMPER FRONT, HEADLAMP ASSY LH, BONNET, FENDER FRONT LH, RAD SUPPORT PANEL LH & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	1		\$1,200.00	\$ 1,200.00		\$ 1,200.00
2	TO SPRAY BUMPER FRONT, BONNET, FENDER FRONT LH & RAD SUPPORT PANEL LH	1		\$1,100.00	\$ 1,100.00		\$ 1,100.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	1		\$150.00	\$ 150.00		\$ 150.00
4	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	1		\$200.00	\$ 200.00		\$ 200.00
5	TO CARRY OUT BODY CAVITY PRESERVATION	1		\$150.00	\$ 150.00		\$ 150.00
6	TO REMOVE & REFIT FENDER QUARTER GLASS FRONT LH	1		\$150.00	\$ 150.00		\$ 150.00
7	TO TRANSFER SENSORS FRONT	1		\$100.00	\$ 100.00		\$ 100.00
PARTS							
1	BUMPER FRONT / BR	1		\$967.80	\$ 967.80		\$ 967.80
2	BUMPER CLIPS / APC	10		\$5.50	\$ 55.00		\$ 55.00
3	BUMPER SIDE RETAINER LH / BR	1		\$104.50	\$ 104.50		\$ 104.50
4	SENSOR FRONT LH X	1		\$503.90	\$ 503.90		\$ 503.90
5	SENSOR BRACKET FRONT / APC	2		\$46.40	\$ 92.80		\$ 92.80
6	HEADLAMP ASSY LH / BR	1		\$6,443.50	\$ 6,443.50		\$ 6,443.50
7	HEADLAMP ASSY COVER LH ?	1		\$145.30	\$ 145.30		\$ 145.30
8	GRILLE FRONT / BR	1		\$2,142.10	\$ 2,142.10		\$ 2,142.10
9	GRILLE BADGE [LOGO] / APC	1		\$118.50	\$ 118.50		\$ 118.50

450
660
39
X
30
X
30

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
10	BONNET X R	1		\$1,194.60	\$ 1,194.60		\$ 1,194.60
11	BONNET LOCK X	1		\$187.20	\$ 187.20		\$ 187.20
12	BONNET HINGE LH X	1		\$81.80	\$ 81.80		\$ 81.80
13	BONNET HINGE RH X	1		\$81.80	\$ 81.80		\$ 81.80
14	FENDER FRONT LH / DR	1		\$1,998.70	\$ 1,998.70		\$ 1,998.70
15	FENDER LINER FRONT LH / TH	1		\$395.00	\$ 395.00		\$ 395.00
16	FENDER LINER CLIPS - MC	10		\$5.50	\$ 55.00		\$ 55.00
17	TOW EYE COVER FRONT LH X	1		\$21.30	\$ 21.30		\$ 21.30
18	FOG LAMP FRONT LH X	1		\$421.30	\$ 421.30		\$ 421.30
19	FOG LAMP FINISHER FRONT LH [WITH CHROME] X	1		\$165.10	\$ 165.10		\$ 165.10
20	BONNET GARNISH [CHROME] / BR	1		\$764.00	\$ 764.00		\$ 764.00
21	WINDSCREEN MOULDING LH [OUTER] / BR	1		\$155.10	\$ 155.10		\$ 155.10
22	FENDER QUARTER GLASS FRONT LH X	1		\$325.50	\$ 325.50		\$ 325.50
23	WASHER TANK SCREEN / CRU	1		\$199.80	\$ 199.80		\$ 199.80
24	RAD SUPPORT PANEL LH ?	1		\$522.80	\$ 522.80		\$ 522.80
25	WINDSCREEN SEALANT X	1		\$100.00	\$ 100.00		\$ 100.00

REMARKS:

SUBTOTAL	\$ 20,292.40	SUBTOTAL	\$ 20,292.40
GST 9%	\$ 1,826.32	GST 9%	\$ 1,826.32
TOTAL	\$ 22,118.72	TOTAL	\$ 22,118.72

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND COMPANY STAMP)

(AUTHORISED SIGNATURE)

Steve (LKK)
 14/11/24, 3:30pm
 w/ IL
 L/S
 by AL M
 5 days



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: