

CARSMITH PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9091 0000/ Email: claims@carsmith.biz

Not Authorized
for
morris
13/11/24
PIP 650
2 days

VEHICLE NO: GBC8817T

MAKE & MODEL: TOYOTA DYNA

DOA: 12.11.2024

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
TAILGATE	1	\$ 1,365.00	11 X
TAILGATE FLOOR PANEL LH	1	\$ 987.00	11 X
SIDE GATE LH	1	\$ 1,850.00	R X
SIDE GATE LOCK LH	1	\$ 280.00	R X
SIDE GATE FLOOR PANEL LH	1	\$ 3,258.00	R X
SIDE GATE STOPPER	1	\$ 50.00	11 X
REAR RIM FENDER LH	1	\$ 528.00	R X
REAR TAIL LAMP LH	1	\$ 640.00	11 X
REAR TAIL LAMP PANEL LH	1	\$ 270.00	11 X
NUMBER PLATE PANEL	1	\$ 490.00	11 X
END STEP PANEL	1	\$ 450.00	11 X
END PANEL	1	\$ 980.00	11 X
END PANEL SIDE BRACKET LH	2	\$ 560.00	11 X
END PANEL SIDE BRACKET STOPPER LH	2	\$ 122.00	11 X

\$ 11,830.00

LESS 25% \$ 2,957.50

SUB TOTAL \$ 8,872.50

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REVERSE SENSOR	1 SET	\$ 480.00	11 X
REAR FLOOR CHECKED PLATE RIVETS	1 SET	\$ 180.00	11 X
TAILGATE STICKER '70KM/H'	1	\$ 45.00	11 X
TOYOTA STICKER	1 SET	\$ 200.00	11 X
JOINT SEALANT	1	\$ 120.00	11 X

SUB TOTAL \$ 1,025.00

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK REAR WIRING AND LIGHTING SYSTEM	1	\$ 100.00	11 X
REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	11 X
REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	1	\$ 150.00	11 X
PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,000.00	300
SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,000.00	350

APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	11 X
-----------------------------------	---	-----------	------

SUB TOTAL \$ 2,470.00

GRAND TOTAL \$ 12,367.50

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: