



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110261/Uvh3e2
75 BRAS BASAH ROAD	Date:	19/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 5420T	Veh. Inspected	SKS 3429Y
Policy No.	-	Coverage	0
Claim No.	MT/1303781-001	Excess	\$0.00
Assign From	JULIE	Assign Date	12/11/2024

2. Vehicle Details

Make & Model	TOYOTA COROLLA ALTIS (A)	C.C	1598
Engine No.	1ZR500020	Year of Reg.	09/04/2015
Chassis No.	MR053REH104530134	Colour	SILVER
Odometer	405777 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55R16	BLACKHAWK	6
L/H Front Tyre	205/55R16	BLACKHAWK	6
R/H Rear Tyre	205/55R16	BLACKHAWK	6
L/H Rear Tyre	205/55R16	BLACKHAWK	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/11/2024	Inspection Date	13/11/2024 (14:01)
Survey held at	JIPPUN TRADING - 1 KAKI BUKIT AVE 6 #01-52 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days