

L H Express Motor Trading

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Sing Onn Electrical Trading
87 Dawson Road
Singapore 141087

Vehicle No : GBE 8736 H
Make/Model : Nissan NV350-2.5D
Year : 2017

NOT Authorized
11 Sep @ 6100h
Penny After Pain
6 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate <i>2101.10</i>		
1 pc	Rear tail-gate inner trim board		
1 pc	Rear tail-gate inner lock		
1 pc	Rear tail-gate glass moulding		
1 pc	Rear tail-gate outer chrome handle <i>460-20</i>		
1 pc	Rear tail-gate emblem - Logo		
1 pc	Rear tail-gate emblem - NV350		
1 pc	Rear tail-gate emblem - Badge		
1 pc	Rear n/s fender inner lower panel <i>368.10</i>		
1 pc	Rear end panel inner		
1 pc	Rear end panel outer		
1 pc	Rear end panel inner garnish		
1 pc	Rear bumper <i>720.60</i>		
1 pc	Rear bumper inner step reinforcement <i>169.90</i>		
1 pc	Rear n/s bumper side retainer		
1 pc	Rear n/s tail-lamp <i>360.10</i>		
1 pc	Rear boot rubber		
1 pc	Front panel		
1 pc	Front windscreen moulding		
1 pc	Front radiator grille		
1 pc	Front bumper		

By	\$2,353.20	✓
Sm	\$355.10	X
R	\$287.60	X
NW	\$95.10	X
MJC/M	\$587.10	✓
Me	\$64.90	—
Me	\$70.10	—
Me	\$72.20	—
By	\$455.60	✓
R	\$478.90	X
R	\$275.10	X
Sm	\$185.20	X
Bu	\$805.60	✓
DIT	\$375.60	—
DIT	\$76.10	—
CM	\$425.10	✓
CM	\$205.60	✓
R	\$1,459.00	X
NW	\$117.60	^
MJC/M	\$655.10	—
-	\$708.50	—
	\$10,108.30	
Less 10 %	\$1,010.83	
	\$9,097.47	

S Nett

1 pc	Front & rear windscreen sealant	
1 pc	Rear reverse sensor	
1 pc	<i>FR</i> Rear no plate	
1 pc	Rear sticker - 70 kmph	
1 pc	Rear sticker - 8 pax	

Me	\$55.00	40SN
Me	\$200.00	—
Me	\$30.00	25SN
Me	\$20.00	15SN
Me	\$20.00	15SN
	\$305.00	
balance c/f	\$9,422.47	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

GBE 8736 H

balance b/f \$9,422.47

Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting.

\$1,500.00 800/

To putty and spray paint

\$1,400.00 1000/

Check & reconnect wiring.

\$35.00 20/

To respray anti-rust proofing treatment

\$150.00 60/

Remove/refit rear windscreen glass

\$120.00 120/

Remove/refit front dashboard to facilitate repair

^^ \$400.00 X

Remove/refit front windscreen to facilitate repair

^^ \$120.00 X

Remove/refit air con blower and to top up gas.

^^ \$280.00 X

Total

\$13,427.47