

L H Express Motor Trading

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Sing Onn Electrical Trading
87 Dawson Road
Singapore 141087

Vehicle No : GBE 8736 H
Make/Model : Nissan NV350-2.5D
Year : 2017

*NOT Authorized
11 Sep @ 6100h
Pickup After Rain
6 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate <i>2101.10</i>	<i>RM</i> \$2,353.20	✓
1 pc	Rear tail-gate inner trim board	<i>Sm</i> \$355.10	X
1 pc	Rear tail-gate inner lock	<i>K</i> \$287.60	X
1 pc	Rear tail-gate glass moulding	<i>NA</i> \$95.10	X
1 pc	Rear tail-gate outer chrome handle <i>460-20</i>	<i>mgcm</i> \$587.10	✓
1 pc	Rear tail-gate emblem - Logo	<i>na</i> \$64.90	—
1 pc	Rear tail-gate emblem - NV350	<i>na</i> \$70.10	—
1 pc	Rear tail-gate emblem - Badge	<i>na</i> \$72.20	—
1 pc	Rear n/s fender inner lower panel <i>368.10</i>	<i>RM</i> \$455.60	✓
1 pc	Rear end panel inner	<i>K</i> \$478.90	X
1 pc	Rear end panel outer	<i>R</i> \$275.10	X
1 pc	Rear end panel inner garnish	<i>Sm</i> \$185.20	X
1 pc	Rear bumper <i>720.60</i>	<i>Bur</i> \$805.60	✓
1 pc	Rear bumper inner step reinforcement <i>169.90</i>	<i>DIY</i> \$375.60	—
1 pc	Rear n/s bumper side retainer	<i>DIY</i> \$76.10	—
1 pc	Rear n/s tail-lamp <i>360.10</i>	<i>CM</i> \$425.10	✓
1 pc	Rear boot rubber	<i>GM</i> \$205.60	<i>502sm 102.80sm</i>
1 pc	Front panel	<i>R</i> \$1,459.00	X
1 pc	Front windscreen moulding	<i>na</i> \$117.60	X
1 pc	Front radiator grille	<i>mgcm</i> \$655.10	—
1 pc	Front bumper	<i>na</i> \$708.50	—
		\$10,108.30	
		Less 10 %	\$1,010.83
			\$9,097.47

S Nett

1 pc	Front & rear windscreen sealant	<i>Me</i> \$55.00	<i>40sm</i>
1 pc	Rear reverse sensor	<i>nd</i> \$200.00	—
1 pc	<i>FR</i> Rear no plate	<i>nd</i> \$30.00	<i>25sm</i>
1 pc	Rear sticker - 70 kmph	<i>na</i> \$20.00	<i>15sm</i>
1 pc	Rear sticker - 8 pax	<i>na</i> \$20.00	<i>15sm</i>
		\$305.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

balance c/f \$9,422.47

GBE 8736 H

balance b/f \$9,422.47

Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting.	\$1,500.00	800L
To putty and spray paint	\$1,400.00	1000L
Check & reconnect wiring.	\$35.00	20L
To respray anti-rust proofing treatment	\$150.00	60L
Remove/refit rear windscreen glass	\$120.00	120L
Remove/refit front dashboard to facilitate repair	nn \$400.00	X
Remove/refit front windscreen to facilitate repair	nn \$120.00	X
Remove/refit air con blower and to top up gas.	nn \$280.00	X
Total	<u>\$13,427.47</u>	