


PHOTOGRAPHS FOR VEHICLE NO. : SME 5215J



PHOTOGRAPHS FOR VEHICLE NO. : SME 5215J




PHOTOGRAPHS FOR VEHICLE NO. : SME 5215J



PHOTOGRAPHS FOR VEHICLE NO. : SME 5215J



PHOTOGRAPHS FOR VEHICLE NO. : SME 5215J



PHOTOGRAPHS FOR VEHICLE NO. : SME 5215J



PHOTOGRAPHS FOR VEHICLE NO. : SME 5215J



PHOTOGRAPHS FOR VEHICLE NO. : SME 5215J




PHOTOGRAPHS FOR VEHICLE NO. : SME 5215J



PHOTOGRAPHS FOR VEHICLE NO. : SME 5215J



PHOTOGRAPHS FOR VEHICLE NO. : SME 5215J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 12 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SME 5215J

