

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/55
SINGAPORE 417883

not Authorized
in
may
13/11/24
5 days. d/s \$5000/
cheapest. After rep.

VEHICLE No :SME 5215J

1PC	FRONT BUMPER	11	\$698.00	X
1PC	FRONT FENDER N/S	10/12/24	\$633.00	✓
1PC	FRONT FENDER INNER SHIELD N/S	10/12/24	\$161.00	✓
1SET	FRONT FENDER INNER SHIELD CLIPS N/S	10/12/24	\$35.00	✓
1PC	FRONT FENDER INNER PANEL N/S	10/12/24	\$620.00	X
1PC	FRONT SHOCK ABSORBER N/S	10/12/24	\$392.00	✓
1PC	FRONT KNUCKLE ARM N/S	10/12/24	\$428.00	✓
1PC	FRONT KNUCKLE ARM BEARING N/S	10/12/24	\$302.00	✓
1SET	FRONT LOWER ARM N/S	10/12/24	\$404.00	✓
1PC	FRONT DRIVE SHAFT N/S	10/12/24	\$890.00	X
1PC	FRONT TIE ROD N/S	10/12/24	\$115.00	✓
1PC	FRONT TIE ROD END N/S	10/12/24	\$166.00	✓
1PC	FRONT CROSS MEMBER	10/12/24	\$1,415.00	X
1PC	FRONT DOOR N/S	10/12/24	\$1,613.00	✓
1PC	FRONT DOOR HINGE N/S	10/12/24	\$98.00	X
1SET	FRONT DOOR FRAME BLACK STICKER N/S	10/12/24	\$68.00	✓
1PC	FRONT DOOR INNER RUBBER N/S	10/12/24	\$165.00	✓
1PC	FRONT DOOR INNER LOCK N/S	10/12/24	\$299.00	X
1PC	FRONT DOOR OUTER PILLAR N/S	10/12/24	\$689.00	X
			\$9,191.00	
			LESS 10%	\$8,271.90

S.NETT

1PC	FRONT SPORT RIM N/S	10/12/24	\$900.00	600 s/w
1PC	FRONT TYRE N/S	10/12/24	\$200.00	X

TO CHECK WIRING	\$50.00	20
TO TRANSFER FRONT DOOR MECHANISM N/S	\$80.00	60
TO SPRAY RUST PFOOFING	\$60.00	✓
TO DIAGNOSTIC & REPROGRAMME SYSTEM	\$100.00	50
TO DISMANTLE & REFIX CHSHION UPHOLSTERY	\$100.00	X
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	\$350.00	150
TO CONDUCT WHEEL ALIGNMENT	\$120.00	100
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$800.00	550
TO PUTTY & SPRAY PAINTING	\$1,200.00	600
TOTAL		\$12,231.90

LKK Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) before survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 4482
102
6033.60
680
1590
6033.8
22
6043