



DICKSON GROUP

Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

Steve (LKK)
14/11/24, 3:39 PM
m k
L/S
by AL ry
10 = 7 days

QUOTATION

QUOTATION FOR

NAME: India International Insurance Pte Ltd
COMPANY NAME: India International Insurance Pte Ltd
STREET ADDRESS: 64 Cecil Street, #04/#05-02, IOB Building
POSTAL CODE: Singapore 049711
PHONE: 6347 6100

DATE: 13/11/2024

REF: SD0824BC0004
VEHICLE NO: SLX9056L
MAKE: HONDA
MODEL: FIT
PREPARED BY: XIANG

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
LABOUR							
1	TO REMOVE & REPLACE TAILGATE, TAILLAMPS, BUMPER REAR, REAR PANEL, BOOT FLOOR, EXHAUST SILENCER REAR & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	1		\$1,400.00	\$ 1,400.00		\$ 1,400.00
2	TO SPRAY TAILGATE, BUMPER REAR, REAR PANEL & BOOT FLOOR	1		\$1,100.00	\$ 1,100.00		\$ 1,100.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	1		\$200.00	\$ 200.00		\$ 200.00
4	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	1		\$150.00	\$ 150.00		\$ 150.00
5	TO CARRY OUT BODY CAVITY PRESERVATION	1		\$100.00	\$ 100.00		\$ 100.00
6	TO REMOVE & REFIT WINDSCREEN REAR	1		\$150.00	\$ 150.00		\$ 150.00
7	TO TRANSFER SENSORS REAR	1		\$100.00	\$ 100.00		\$ 100.00
PARTS							
1	TAILGATE / DD	1		\$851.80	\$ 851.80		\$ 851.80
2	TAILGATE LOCK / x nn	1		\$157.20	\$ 157.20		\$ 157.20
3	TAILGATE BADGE [FIT] / nk	1		\$37.80	\$ 37.80		\$ 37.80
4	TAILGATE BADGE [LOGO] x nn	1		\$22.50	\$ 22.50		\$ 22.50
5	WINDSCREEN MOULDING REAR / nk	1		\$115.30	\$ 115.30		\$ 115.30
6	REAR PANEL ? / DD	1		\$397.40	\$ 397.40		\$ 397.40
7	BUMPER REAR / DD	1		\$529.80	\$ 529.80		\$ 529.80
8	BUMPER CLIPS / nk	10		\$4.20	\$ 42.00		\$ 42.00

~~444~~
1200

~~422~~
1000

30

X

30

120

30

2410

/

/

/

/

/

301

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
9	BUMPER BRACKET REAR LH / BR	1		\$27.50	\$ 27.50		\$ 27.50 /
10	BUMPER BRACKET REAR RH / BR	1		\$27.50	\$ 27.50		\$ 27.50 /
11	BUMPER MOULDING REAR LH ? x nn	1		\$38.50	\$ 38.50		\$ 38.50
12	BUMPER MOULDING REAR RH ? / Cut	1		\$38.50	\$ 38.50		\$ 38.50 /
13	EXHAUST SILENCER REAR ? x nn	1		\$498.50	\$ 498.50		\$ 498.50
14	BUMPER MOULDING REAR CENTRE / Cut	1		\$69.70	\$ 69.70		\$ 69.70 /
15	TAILGATE COVERBOARD ? x nn	1		\$125.70	\$ 125.70		\$ 125.70
16	COVERBOARD CLIPS ? x nn	10		\$4.20	\$ 42.00		\$ 42.00
17	REAR PANEL INNER TRIM ? / CRU	1		\$85.90	\$ 85.90		\$ 85.90 /
18	CARPET BOOT FLOOR ? x nn	1		\$330.80	\$ 330.80		\$ 330.80
19	BOOT FLOOR ? / DD	1		\$1,033.70	\$ 1,033.70		\$ 1,033.70 /
20	TAILAMP OUTER LH ? / CUT	1		\$351.20	\$ 351.20		\$ 351.20 /
21	TAILAMP OUTER RH ? / CUT	1		\$351.20	\$ 351.20		\$ 351.20 /
22	TAILAMP INNER LH ? x nn	1		\$160.70	\$ 160.70		\$ 160.70
23	TAILAMP INNER RH ? x nn	1		\$160.70	\$ 160.70		\$ 160.70
24	SENSOR BRACKER REAR ? x nn	2		\$50.00	\$ 100.00		\$ 100.00
25	SENSOR REAR LH / shok	1		\$67.50	\$ 67.50		\$ 67.50 /
26	SENSOR REAR RH / shok	1		\$67.50	\$ 67.50		\$ 67.50 /
27	WINDSCREEN SEALANT / MC	1		\$100.00	\$ 100.00		\$ 100.00 401
SUBTOTAL					\$ 9,030.90	SUBTOTAL	\$ 9,030.90
GST 9%					\$ 812.78	GST 9%	\$ 812.78
TOTAL					\$ 9,843.68	TOTAL	\$ 9,843.68

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

4122.30
-20%
3297.84

(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)

5707.84 + 315.68 = 6023.52

L/S - 4818.81
= 4800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



DICKSON GROUP
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

QUOTATION

QUOTATION FOR

NAME: India International Insurance Pte Ltd
COMPANY NAME: India International Insurance Pte Ltd
STREET ADDRESS: 64 Cecil Street, #04/#05-02, IOB Building
POSTAL CODE: Singapore 049711
PHONE: 6347 6100

DATE: 22/11/2024

REF: SUPPLEMENTARY
VEHICLE NO: SLX9056L
MAKE: HONDA
MODEL: FIT
PREPARED BY: XIANG

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	<u>PARTS</u>						
1	BUZZER / BR	1		\$81.60	\$ 81.60		\$ 81.60 /
2	CARGO BOX (Spare tyre foam) / DEF1			\$220.70	\$ 220.70		\$ 220.70 /
3	TAILGATE WEATHERSTRIP / TN	1		\$92.30	\$ 92.30		\$ 92.30 /
SUBTOTAL					\$ 394.60	SUBTOTAL	\$ 394.60
GST 9%					\$ 35.51	GST 9%	\$ 35.51
TOTAL					\$ 430.11	TOTAL	\$ 430.11

REMARKS:

Steve (LKK)
22/11/24

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

394.60
-20%
315.68



(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)