



DICKSON GROUP

Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

Steve (LKK)
14/11/24, 3:39 PM
m k
L/S
by AL ry
7 days

QUOTATION

QUOTATION FOR

NAME: India International Insurance Pte Ltd
COMPANY NAME: India International Insurance Pte Ltd
STREET ADDRESS: 64 Cecil Street, #04/05-02, IOB Building
POSTAL CODE: Singapore 049711
PHONE: 6347 6100

DATE: 13/11/2024

REF: SD0824BC0004
VEHICLE NO: SLX9056L
MAKE: HONDA
MODEL: FIT
PREPARED BY: XIANG

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
LABOUR							
1	TO REMOVE & REPLACE TAILGATE, TAILLAMPS, BUMPER REAR, REAR PANEL, BOOT FLOOR, EXHAUST SILENCER REAR & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	1		\$1,400.00	\$ 1,400.00		\$ 1,400.00
2	TO SPRAY TAILGATE, BUMPER REAR, REAR PANEL & BOOT FLOOR	1		\$1,100.00	\$ 1,100.00		\$ 1,100.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	1		\$200.00	\$ 200.00		\$ 200.00
4	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	1		\$150.00	\$ 150.00		\$ 150.00
5	TO CARRY OUT BODY CAVITY PRESERVATION	1		\$100.00	\$ 100.00		\$ 100.00
6	TO REMOVE & REFIT WINDSCREEN REAR	1		\$150.00	\$ 150.00		\$ 150.00
7	TO TRANSFER SENSORS REAR	1		\$100.00	\$ 100.00		\$ 100.00
PARTS							
1	TAILGATE / DP	1		\$851.80	\$ 851.80		\$ 851.80
2	TAILGATE LOCK	1		\$157.20	\$ 157.20		\$ 157.20
3	TAILGATE BADGE [FIT] - MK	1		\$37.80	\$ 37.80		\$ 37.80
4	TAILGATE BADGE [LOGO] X	1		\$22.50	\$ 22.50		\$ 22.50
5	WINDSCREEN MOULDING REAR - MK	1		\$115.30	\$ 115.30		\$ 115.30
6	REAR PANEL ?	1		\$397.40	\$ 397.40		\$ 397.40
7	BUMPER REAR / DP	1		\$529.80	\$ 529.80		\$ 529.80
8	BUMPER CLIPS - MK	10		\$4.20	\$ 42.00		\$ 42.00

400
400
30
X
30
120
30
30
30

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
9	BUMPER BRACKET REAR LH / BR	1		\$27.50	\$ 27.50		\$ 27.50
10	BUMPER BRACKET REAR RH / BR	1		\$27.50	\$ 27.50		\$ 27.50
11	BUMPER MOULDING REAR LH ?	1		\$38.50	\$ 38.50		\$ 38.50
12	BUMPER MOULDING REAR RH ?	1		\$38.50	\$ 38.50		\$ 38.50
13	EXHAUST SILENCER REAR ?	1		\$498.50	\$ 498.50		\$ 498.50
14	BUMPER MOULDING REAR CENTRE / (GT) 1	1		\$69.70	\$ 69.70		\$ 69.70
15	TAILGATE COVERBOARD ?	1		\$125.70	\$ 125.70		\$ 125.70
16	COVERBOARD CLIPS ?	10		\$4.20	\$ 42.00		\$ 42.00
17	REAR PANEL INNER TRIM ?	1		\$85.90	\$ 85.90		\$ 85.90
18	CARPET BOOT FLOOR ?	1		\$330.80	\$ 330.80		\$ 330.80
19	BOOT FLOOR ?	1		\$1,033.70	\$ 1,033.70		\$ 1,033.70
20	TAILAMP OUTER LH ?	1		\$351.20	\$ 351.20		\$ 351.20
21	TAILAMP OUTER RH ?	1		\$351.20	\$ 351.20		\$ 351.20
22	TAILAMP INNER LH ?	1		\$160.70	\$ 160.70		\$ 160.70
23	TAILAMP INNER RH ?	1		\$160.70	\$ 160.70		\$ 160.70
24	SENSOR BRACKER REAR ?	2		\$50.00	\$ 100.00		\$ 100.00
25	SENSOR REAR LH / shok	1		\$67.50	\$ 67.50		\$ 67.50
26	SENSOR REAR RH / shok	1		\$67.50	\$ 67.50		\$ 67.50
27	WINDSCREEN SEALANT / MC	1		\$100.00	\$ 100.00		\$ 100.00
SUBTOTAL					\$ 9,030.90	SUBTOTAL	\$ 9,030.90
GST 9%					\$ 812.78	GST 9%	\$ 812.78
TOTAL					\$ 9,843.68	TOTAL	\$ 9,843.68

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____