

ESTIMATE

MS FIRST CAPITAL INSURANCE LIMITED
 16, RAFFLES QUAY,
 #42-01 HONG LEONG BUILDING
 SINGAPORE 048581
 Tel: 65073848
 Fax: 65073849
 Attn: MOTOR CLAIM DEPARTMENT

No. : ES.24110005
 Date : 13/11/2024
 Ref. : GBM3719Z
 Staff : SUSAN
 Terms : Progress Claim
 Job :

VEH NO : GBM3719Z MODEL : SHINERAY X30LEV V2.0 CHASSIS NO : LM60CKD2X3PX002382
DOA : 07/11/2024

SNo	Description	Quantity	Unit Price	Amount	
	PARTS : -				
1	WIPER GARNISH	1	540.00	540.00	cut
2	WIPER GARNISH CLIPS	1 SET	50.00	50.00	nec
3	WIPER BLADE	2	0.00	0.00	nn
4	WIPER ARM	2	0.00	0.00	nn
5	WIPER HOSE	2	0.00	0.00	nn
6	WIPER RUBBER	1	0.00	0.00	nn
7	WIPER TANK	1	300.00	300.00	deformed
8	FRONT WINDSCREEN	1	0.00	0.00	nn
9	FRONT WINDSCREEN MOULDING	1	0.00	0.00	nn
10	FRONT BONNET	1	2,400.00	2,400.00	bent
11	FRONT BONNET HINGE	2	234.00	468.00	bent
12	FRONT BONNET EMBLEM LOGO	1	360.00	360.00	nec
13	FRONT BONNET LOCK	1	360.00	360.00	bent
14	FRONT BONNET LOCK CATCH HOOK	1	285.00	285.00	bent
15	FRONT BONNET LOCK CABLE	1	0.00	0.00	nn
16	FRONT BONNET ABSORBER	2	0.00	0.00	nn
17	FRONT BONNET STOPPER	3	0.00	0.00	nn
18	FRONT BONNET SEAL	1	0.00	0.00	nn
19	FRONT GRILLE	2	495.00	990.00	cracked
20	FRONT GRILLE FRAME	2	555.00	1,110.00	cracked
21	FRONT GRILLE INNER GARNISH	2	510.00	1,020.00	distorted
22	FRONT GRILLE CLIPS	2 SET	50.00	100.00	nec
23	HEADLAMP ASSY LH/RH	2	1,500.00	3,000.00	cracked

ESTIMATE

MS FIRST CAPITAL INSURANCE LIMITED
 16, RAFFLES QUAY,
 #42-01 HONG LEONG BUILDING
 SINGAPORE 048581
 Tel: 65073848
 Fax: 65073849
 Attn: MOTOR CLAIM DEPARTMENT

No. : ES.24110005
 Date : 13/11/2024
 Ref. : GBM3719Z
 Staff : SUSAN
 Terms : Progress Claim
 Job :

VEH NO : GBM3719Z MODEL : SHINERAY X30LEV V2.0 CHASSIS NO : LM60CKD2X3PX002382
DOA : 07/11/2024

SNo	Description	Quantity	Unit Price	Amount	
24	SUPPORT LOWER PANEL	1	555.00	555.00	bent
25	FRONT BUMPER	1	2,370.00	2,370.00	deformed
26	FRONT BUMPER REINFORCEMENT	1	570.00	570.00	bent
27	FRONT BUMPER SPONGE	1	0.00	0.00	nn
28	FRONT BUMPER RETAINER	2	75.00	150.00	distorted
29	FRONT BUMPER GRILLE	1	375.00	375.00	missing
30	FRONT BUMPER FOG LAMP	2	525.00	1,050.00	cracked
31	FRONT BUMPER FOG LAMP COVER LH nn RH cracked	2	234.00	468.00	
32	FRONT BUMPER INNER BAR	1	474.00	474.00	bent
33	FRONT CHASSIS MEMBER	2	0.00	0.00	Repair
34	FRONT FENDER LH/RH	2	480.00	960.00	bent
35	FRONT FENDER EMBLEM LH/RH	2	105.00	210.00	nec
36	FRONT FENDER INNER SHIELD RH nn LH cut	2	135.00	270.00	
37	FRONT FENDER CLIPS	2 SETS	50.00	20 100.00	nec
38	FRONT FENDER APRON PANEL	1	0.00	0.00	Repair
39	SUPPORT PANEL	1	2,040.00	2,040.00	bent
40	A PILLAR	1	0.00	0.00	Repair
41	FIREWALL	1	0.00	0.00	Repair
42	AIR CONDENSER	1	1,480.00	1,480.00	bent
43	AIR-CON LOW PRESSURE PIPE	1	400.00	400.00	bent
44	AIR-CON HIGH PRESSURE PIPE	1	400.00	400.00	bent
45	AIR-CON RECEIVE PIPE	1	0.00	0.00	nn
46	AIR-CON LIQUIP PIPE	1	0.00	0.00	nn

ESTIMATE

MS FIRST CAPITAL INSURANCE LIMITED
 16, RAFFLES QUAY,
 #42-01 HONG LEONG BUILDING
 SINGAPORE 048581
 Tel: 65073848
 Fax: 65073849
 Attn: MOTOR CLAIM DEPARTMENT

No. : ES.24110005
 Date : 13/11/2024
 Ref. : GBM3719Z
 Staff : SUSAN
 Terms : Progress Claim
 Job :

VEH NO : GBM3719Z MODEL : SHINERAY X30LEV V2.0 CHASSIS NO : LM60CKD2X3PX002382
DOA : 07/11/2024

SNo	Description	Quantity	Unit Price	Amount	
47	AIR-CON DISCHARGE PIPE	1	0.00	0.00	nn
48	AIR-CON SUCTION PIPE	1	0.00	0.00	nn
49	AIR-CON BLOWER ASSY	1	2,040.00	2,040.00	cracked
50	AIR-CON COOLING COIL ASSY	1	420.00	420.00	cracked
51	AIR-CON COMPRESSER	1	0.00	0.00	nn
52	RADIATOR	1	1,470.00	1,470.00	bent
53	RADIATOR SPARE TANK	1	210.00	210.00	deformed
54	RADIATOR TOP HOSE	1	0.00	0.00	nn
55	RADIATOR BOTTOM HOSE	2	0.00	0.00	nn
56	BRAKE OIL TANK	1	0.00	0.00	nn
57	FAN BLADE	1	240.00	240.00	cut
58	FAN COWLING	1	240.00	240.00	cracked
59	FAN MOTOR	1	450.00	450.00	jammed
60	HEATER ASSY	1	0.00	0.00	nn
61	HEATER FRAME	1	0.00	0.00	nn
62	HEATER HOUSING	1	0.00	0.00	nn
63	HEATER COVER	1	0.00	0.00	nn
64	DASHBOARD	1	2,340.00	2,340.00	cracked
65	INTRUSMENT PANEL	1	1,950.00	1,950.00	distorted
66	DRIVER AIR BAG	1	1,650.00	1,650.00	activated
67	PASSANGER AIR BAG	1	1,650.00	1,650.00	activated
68	AIR BAG ECU	1	1,770.00	1,770.00	activated
69	STEERING WHEEL	1	0.00	0.00	nn
70	STERRING ANGLE SENSOR	1	435.00	435.00	activated

ESTIMATE

MS FIRST CAPITAL INSURANCE LIMITED
 16, RAFFLES QUAY,
 #42-01 HONG LEONG BUILDING
 SINGAPORE 048581
 Tel: 65073848
 Fax: 65073849
 Attn: MOTOR CLAIM DEPARTMENT

No. : ES.24110005
 Date : 13/11/2024
 Ref. : GBM3719Z
 Staff : SUSAN
 Terms : Progress Claim
 Job :

VEH NO : GBM3719Z MODEL : SHINERAY X30LEV V2.0 CHASSIS NO : LM60CKD2X3PX002382
DOA : 07/11/2024

SNo	Description	Quantity	Unit Price	Amount	
71	SEAT BELT LH/RH LH nn RH activated	2	1,680.00	3,360.00	
72	SEAT BELT BRACKET LH/RH	2	0.00	0.00	nn
73	SEAT BELT HEIGH ADJUSTER LH/RH	2	0.00	0.00	nn
74	SEAT BELT COVER LH/RH	2	0.00	0.00	nn
75	HORN	1	150.00	150.00	cracked
76	ABS PUMP	1	3,450.00	3,450.00	nn
77	ABS PIPE	52	580.00	1160 3,480.00	bent
78	FUSE BOX	1	750.00	750.00	cut
79	FRONT SHOCK ABSORBER	1	0.00	0.00	nn
80	FRONT SHOCK ABSORBER STOPPER	1	0.00	0.00	nn
81	FRONT SHOCK ABSORBER COVER	1	0.00	0.00	nn
82	FRONT WHEEL RIM	2	0.00	0.00	nn
83	FRONT SHOCK ABSORBER BEARING	1	0.00	0.00	nn
84	FRONT STABILIZER LINK	1	0.00	0.00	nn
85	FRONT KNUCKLE ARM	1	0.00	0.00	nn
86	FRONT WHEEL BEARING	2	0.00	0.00	nn
87	FRONT WHEEL HUB	2	0.00	0.00	nn
88	WIRING HARDNESS	1	0.00	0.00	nn
89	FRONT RADAR SENSOR	1	0.00	0.00	nn
	TOTAL			48,910.00	
	PARTS ITEM LESS 10%	1	-4,891.00	(4,891.00)	
	SUBTOTAL			44,019.00	
	SPECIAL NETT ITEM :-				

L 41091.00
 - 1070
 37685.30

R & S Autoclaim Pte Ltd

GST & Co Reg No. : 202245519N
 Tel : (65) 6264 7001
 Fax : (65) 6264 7002
 Email : rnsautoclaim@rnseng.com.sg
 Address : No.13 Pioneer Sector 1,
 Singapore 628424

ESTIMATE

MS FIRST CAPITAL INSURANCE LIMITED
 16, RAFFLES QUAY,
 #42-01 HONG LEONG BUILDING
 SINGAPORE 048581
 Tel: 65073848
 Fax: 65073849
 Attn: MOTOR CLAIM DEPARTMENT

No. : ES.24110005
 Date : 13/11/2024
 Ref. : GBM3719Z
 Staff : SUSAN
 Terms : Progress Claim
 Job :

VEH NO : GBM3719Z MODEL : SHINERAY X30LEV V2.0 CHASSIS NO : LM60CKD2X3PX002382
DOA : 07/11/2024

SNo	Description	Quantity	Unit Price	Amount	
1	FRONT NUMBER PLATE WITH CASING mis ✓	1	55.00	55.00	mis
2	RADIO	1	0.00	0.00	X nn
3	TYRE X	2	285.00	570.00	X nn
4	FRONT WINDSCREEN SEALANT X	1	80.00	80.00	X nn
5	AIR-CON GAS	1	150.00	150.00	100
6	RADIATOR COOLANT	1	40.00	40.00	
7	BRAKE FLUID OIL	1	60.00	60.00	nn
	LABOUR :-			SN \$185	
1	TO REMOVE AND INSTALL FRONT WINDSCREEN	1	180.00	180.00	X nn
2	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREA. FRONT PORTION	1	2,800.00	2,800.00	1400 1800
3	TO PUTTY, RE-SPRAY AND POLISH ON ACCIDENT AREA. FRONT PORTION	1	2,200.00	2,200.00	1400 1600
4	TO CHECK AND RECTIFY WIRING CONNECT AND DISCONNECT	1	150.00	150.00	50
5	TO SPRAY RUST PROOFING ON AFFECTED AREA	1	180.00	180.00	50
6	TO REMOVE AND INSTALL AIR-CON CONDENSER AND RADIATOR	1	180.00	180.00	120
7	TO REMOVE AND INSTALL UNDERCARRIGE	1	180.00	180.00	X nn
8	TO REMOVE AND INSTALL INNER SEAT & UPHOLSTORY TO ASSIST WORK LOAD	1	180.00	180.00	X nn
9	TO BALANCING, REALIGN WHEEL ALIGNMENT	1	250.00	250.00	X nn
10	TO STRAIGHTEN, PANEL BEAT & REALIGN FRONT CHASSIS MEMBER	1	480.00	480.00	200
11	TO CHECK DIAGOSTICS OF VEHICLE MANAGEMENT/CONTROL RESET MEMORIES TO SPECIFICATION ETC	1	900.00	900.00	300

R & S Autoclaim Pte Ltd

GST & Co Reg No. : 202245519N
 Tel : (65) 6264 7001
 Fax: (65) 6264 7002
 Email : msautoclaim@mseng.com.sg
 Address : No.13 Pioneer Sector 1,
 Singapore 628424

ESTIMATE

MS FIRST CAPITAL INSURANCE LIMITED
 16, RAFFLES QUAY,
 #42-01 HONG LEONG BUILDING
 SINGAPORE 048581
 Tel: 65073848
 Fax: 65073849
 Attn: MOTOR CLAIM DEPARTMENT

No. : ES.24110005
 Date : 13/11/2024
 Ref. : GBM3719Z
 Staff : SUSAN
 Terms : Progress Claim
 Job :

VEH NO : GBM3719Z MODEL : SHINERAY X30LEV V2.0 CHASSIS NO : LM60CKD2X3PX002382
 DOA : 07/11/2024

SNo	Description	Quantity	Unit Price	Amount
12	TO REMOVE AND REFIT DASHBOARD	1	450.00	180 450.00
13	TO REMOVE & FLUSH BRAKE SYSTEM	1	280.00	X nn 280.00
14	TO REMOVE AND REFIT AIR-BAG SYSTEM AND UNIT	1	500.00	250 500.00
15	TO REMOVE AND INSTALL RADIO	1	280.00	50 280.00
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: Tan Kahin 97495749 10 days WP 13/11/24 330pm 12 days c/s Resurvey after repair. Repair limit \$25K. tan kahin c1khaauto.com				4600 P- 37625.30 SN- 185.00 L- 4600.00 42410.30 2096 33928.24 45 \$33950
Sum of Singapore Dollars Eleven Thousand Fifty Eight And Cents Five Only			Amt S\$ 10,145.00 9% GST 913.05 Total S\$ 11,058.05	