



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: HARMINDER		Ref: CS/FCI24110266/Tvp3e2(N) Date: 04/04/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 431D	Veh. Inspected	GBM 3719Z
Policy No.	D-24101860MFCT	Coverage (\$)	0.00
Claim No.	D24009866MFCT	Excess (\$)	0.00
Assign From	HARMINDER	Assign Date	13/11/2024
2. Vehicle Particulars & Condition			
Make & Model	SHINERAY X30LEV	c.c	0
Engine No.	HIDDEN	Year of Reg.	2023
Chassis No.	LM6CKD2X3PX002382	Colour	RED
Odometer	31221 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/70 R14	HAIDA	6 mm
L/H Front Tyre	175/70 R14	HAIDA	6 mm
R/H Rear Tyre	175/70 R14	HAIDA	6 mm
L/H Rear Tyre	175/70 R14	HAIDA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/11/2024	Inspection Date	13/11/2024
Survey held at	R&S AUTOCLAIM PTE LTD 13 PIONEER SECTOR 1, SINGAPORE 628424		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	