

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No third party modification is allowed
- Supplementary item(s) must be resurveyed and is subject to that approval from Insurance Company

Acknowledged by Repairer

GST REG. NO : M28Signature 020081 - X

Date:

E S T I M A T E

1 Nov 2024



Estimate No. : b1 71674
Date Estimated : 01/11/2024
Prepared By : Yap Mee Key

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Sharon Koh Kai Ling (Xu Kailing)
97 Pasir Ris Heights
#15-25

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 519290

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME1109J	WBY72EG0805Z58476	25/06/2024	IX1 EDRIVE20 SAV	12

DESCRIPTION

To replace front left wheel arch, make good front left fender and attachments.

To respray front left fender and affecte areas.

To test drive, check electrical for pro- per function.

Sundries.

VALUE

850 1,275.00

1,180.00

X119 177.00

40 30 40.00

Total Labour 1: 2,672.00

DESCRIPTION

LH WHEEL HOUSING STRUT EXTENSION X119
LH SIDE SILL TRIM PANEL PRIMED (LIN X119

QTY	PRIC	VALUE
1	194.65	194.65
1	409.40	409.40
Total Parts :		604.05

Date & Time 27/11/24 Excess SS

Surveyor's Name RASAM Sign

Surveyor's Tel 90010688 Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend 2 days

Pay after repair



Labour 1	:	2,672.00
Parts	:	604.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	294.84
Grand Total	:	3,570.89

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **