



Final Report

Estimate No. : **b1 71674**
 Date Estimated : **01/11/2024**
 Prepared By : **Yap Mee Key**

Page No. :

- **ESTIMATE REPAIR FOR** -
Sharon Koh Kai Ling (Xu Kailing)
97 Pasir Ris Heights
#15-25

- **ACCOUNT** - **49636**
Smrt Taxis Pte Ltd
60 Woodlands Industrial Park E4

Singapore 757705

Singapore 519290

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SME1109J	WBY72EG0805Z58476	25/06/2024	IX1 EDRIVE20 SAV	12

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To make good the front LH fender include carrying out other necessary repairs caused by the accident	850.00		850.00
To respray front LH fender	1,180.00		1,180.00
* To carry out diagnostic, test modules, de-energise and re-energise the high voltage system by BMW qualified expert (For Full EV)	531.00		531.00
Sundries	40.00		40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
NO PARTS				

SUPPLEMENTARY ITEMS

Total Labour :	2,601.00
Total Parts :	
Total Labour & Parts (before GST) :	2,601.00
Deduction for Excess :	
Total Repair Costs less Excess:	2,601.00
GST @9%:	234.09
Grand Total :	2,835.09

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
 Co Reg No. 197401559W

