



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/11/2024

User ID : kokkhoon

Section A - Accident Details	
Registration Number	SBS3611T
Case Reference Number	BUS/10/24/8014
Registration Date	12/7/2013
Company Type	SMRT Buses Ltd
Make	VOLVO
Model	B9TL
Name of Driver	Lee Heng Chong
Type of Accident	Side Swipe
Accident Date and Time	30/10/2024 4:50 PM
Accident Reported Date and Time	7/11/2024 9:08 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SBS3611T - FRONT LEFT BUMPER GBH6202D (TP) - INSURED WITH ECICS Limited
Prepared Date and Time	12/11/2024 2:59 PM
Chassis Number	YV3S4P928DA161708
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$1,213.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,949.00	\$0.00
Lump Sum Total	\$3,950.00	\$0.00
Number of Repair Days	5.0	
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	12/11/2024 3:22 PM	
Signature		
Remarks		

Steve (LKK)
13/11/24, 3.30 pm
Without Prejudice
L/S
Resurvey After Spray
4 days

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/11/2024

User ID : kokkhoon

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$2,120.00				1590		
Total Labour			\$2,120.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$616.00				446		
Total Spray Painting & Panel Beating			\$616.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012093			DOME,FRONT:LOWER,CLASS 2,FOR VOLVO B9TL	1.00	\$3,391.95	100.00	\$0.00	Replace	x Repair
6012094	Body	ATP-03155	N/S CORNER BUMPER	1.00	\$974.78	10.00	\$877.30	Replace	/ BR
6012097	Body	ATP-02807	N/S CORNER DEFLECTOR	1.00	\$328.33	10.00	\$295.50	Replace	/ BR
6012099	Body	ATP-02812	FRT N/S LIGHT BEZEL	1.00	\$298.28	10.00	\$268.45	Replace	/ MIS
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	/ Nec
Total					\$5,068.34		\$1,516.25		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									