

ASS. REC. BY:

REF:

AG21 CS/AG124110272/Knp3

C

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 38k

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLJ 9373U Yr Regn: 12, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Volkswagen Touan C.C 1395 Wagon

Colour: White A/C: Insured / Std / NI / NA

Sp.Reading: 218859 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WVG 8881T81HW 044806

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 11/11/24 D.O.I. 14/11/2024

Survey held at \_\_\_\_\_

Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
18/11 11pm	5300 Cash (Red. \$10320.40, 66%)

Date/Time, File Pass to?  : Prell. Report  : Final Report

1) Date/Time, File Return to?   
 2) \_\_\_\_\_

Days Of Repair: 4   
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ )   
  : Interview (\$ )   
  : Tech Invs (\$ )   
  : Weekend (\$ )

Survey Fee:
Transportation
S + RS. SI
Fees
Others
TOTAL

Report Format : \_\_\_\_\_   
 Lump Sum / I.B.I: (\$ \_\_\_\_\_)



# MOTORSPORTS

JD MOTORSPORTS PTE LTD  
25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 12/11/2024  
VEHICLE : SLJ9373U  
MAKE/MODEL : VOLKSWAGEN TOURAN  
CHASSIS NO : WVG22211ZHW044806  
MILLAGE :  
TYRE SIZE :  
DOA : 11/11/2024  
3RD INSURANCE : BUDGET DIRECT

*Not Authorized  
61 Rep @ 5300/-  
Picking After Paiming  
4 days*

List items

01 PC	REAR BUMPER	1462.70	Ddt/cm	\$ 1,862.00	✓
01 PC	REAR BUMPER DISFUFR	755.20	pd/cm	\$ 1,015.00	✓
01 PC	REAR BUMPER TOWING COVER		\$ 1m	95.80	X
01 PC	REAR BUMPER INNER BRACKET	272	\$CM	562.50	✓
01 PC	REAR BUMPER LH LOWER TAIL LAMP BRACKET		\$ 1/2	289.10	X
01 PC	REAR BUMPER RH LOWER TAIL LAMP BRACKET		\$ 1/2	289.10	X
02 PC	REAR BUMPER SIDE RETAINER @ \$185.20		\$ 1/2	370.40	X
01 PC	REAR BUMPER REFELCTOR LH		\$ 1/2	211.60	X
01 PC	REAR BUMPER REFELCTOR RH		\$ 1/2	211.60	X
01 PC	REAR END PANEL		\$ 1/2	1,643.20	X
01 PC	REAR END PANEL TOP GANISH	325.10	mg/cm	\$ 364.30	✓
01 PC	REAR REINFORCEMENT		\$ R	853.10	X
01 PC	REAR TAIL GATE	1723.90	\$ 1/2	2,361.40	✓
01 PC	REAR TAIL GATE EMBLEM (TOURAN)	126.15	\$ 1/2	175.60	✓
01 PC	REAR TAIL GATE EMBLEM (280 TSI)	136	\$ 1/2	185.30	✓
01 PC	REAR TAIL GATE INNER LOCK	133	\$ 1/2	632.50	✓
01 PC	REAR TAIL GATE INNER TRIM BOARD		mg/cm	833.90	✓
<b>TOTAL PARTS COST</b>				<b>\$ 11,956.40</b>	

SPECIAL NETT:

02 PC	PARKING SENSOR @ \$380.00		pd	\$ 760.00	4x 2005N
06 PC	REAR BUMPER CLIP @ \$12.00		1/2m	72.00	501m
06 PC	REAR BUMPER DISFUFR CLIP @ \$12.00		1/2m	72.00	401m
10 PC	REAR TAIL GATE INNER TRIM CLIP @ \$12.00		1/2m	120.00	X
01 PC	WINDSCREEN SEALANT		\$	80.00	401m
01 PC	PANEL SEALANT		\$ 1/2	60.00	X
01 PC	NUMBER PLATE		\$ 1/2	30.00	X
01 PC	NUMBER PLATE COVER		\$ 1/2	20.00	X
<b>TOTAL SPECIAL NETT</b>				<b>\$ 1,214.00</b>	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$ 1,000.00	500l
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	\$ 600.00	400l
3. TO SUPPLY DIAGNOTIC & RESET FAULT CODE TO FACILITATE THE REPAIR	\$ 250.00	X 50l 60
4. TO SUPPLY LABOUR TO DISMANTLE & REFIX INNER UPHOLSTER	\$ 200.00	
5. TO SUPPLY LABOUR TO DISMANTLE & REFIX REAR WINDSCREEN	\$ 250.00	120l
6. TO SUPPLY LABOUR TO REWIRE ACCIDENT AFFECT AREA	\$ 150.00	20l
<b>TOTAL LABOUR</b>	<b>\$ 2,450.00</b>	

**TOTAL PARTS**  
**TOTAL SPECIAL NETT**  
**TOTAL LABOUR**  
**TOTAL COST OF REPAIR**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No liability classification is allowed
- Subject to any item(s) must be resurveyed and is subject to final approval from Insurance Company

\$ 11,956.40  
\$ 1,214.00  
\$ 2,450.00  
**\$ 15,620.40**