

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 3
SINGAPORE 038988

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Estimate No: EST2400434
Date: 12 Nov 2024

Veh Reg No: SMP5613K
Make/Model: MAZDA MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Chasis No: JM6BM42A8G0328506
Reg. Date: 29/12/2015
Your Ref No: SBP339R

Claim Type: Third Party
Accident Date: 11/11/2024
TP Veh Reg No: SBP339R

Estimate Repair Cost to Vehicle No :SMP5613K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC REAR BUMPER	1,228.60	
2	1 PC REAR BUMPER REINFORCEMENT	564.20	
3	2 PCS REAR BUMPER SIDE RETAINER	112.80	
4	1 PC REAR BUMPER REFLECTOR - LH	106.20	
5	1 PC REAR TOWING COVER	51.60	
6	1 PC REAR BUMPER LOWER GARNISH LH	79.60	
7	1 PC BOOT LID	1,265.60	
8	1 PC BOOTLID LOGO	85.10	
9	1 PC BOOTLID "MAZDA" EMBLEM	66.20	
10	1 PC BOOTLID "SKYACTIV" EMBLEM	74.40	
11	1 PC BOOT LID LAMP LH	399.80	
12	1 PC BOOT LID RUBBER	193.20	
13	1 PC REAR FENDER LH	1,546.30	
14	1 PC REAR FENDER COWLING LH	108.60	
15	1 PC REAR FENDER LH LOWER SIDE PANEL	262.70	
16	1 PC REAR FENDER INNER TRIM LH	298.70	
17	1 PC REAR VENTILATION AIR DUCT	79.40	
18	1 PC REAR WINDSCREEN RUBBER	124.50	
19	1 PC TAIL LAMP LH	584.60	
20	1 PC TAIL LAMP PANEL LH	277.40	
21	1 PC REAR PANEL	681.60	
22	1 PC REAR PANEL TRIM	184.00	
23	1 PC REAR SPARE TYRE HARDBOARD	396.10	
24	1 PC SPARE TYRE PANEL LH SPONGE	297.40	
25	1 PC EXHAUST PIPE	786.20	
26	2 PCS EXHAUST PIPE MOUNTING	48.20	
		9,903.00	
	Less 20%	1,980.60	7,922.40

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 3
SINGAPORE 038988

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Estimate No: EST2400434
Date: 12 Nov 2024

Veh Reg No: SMP5613K
Make/Model: MAZDA MAZDA3 4-
DOOR SEDAN 1.5L
SP.6EAT
Chasis No: JM6BM42A8G0328506

Claim Type: Third Party
Accident Date: 11/11/2024
TP Veh Reg No: SBP339R

Reg. Date: 29/12/2015
Your Ref No: SBP339R

Estimate Repair Cost to Vehicle No :SMP5613K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Special Net			
27	1 SET REAR BUMPER CLIPS	40.00	
28	1 SET REVERSE SENSORS	280.00	
29	1 PC REAR BOOTLID SPOILER	480.00	
30	1 SET REAR LH FENDER COWLING CLIPS	40.00	
31	1 SET REAR FENDER INNER TRIM CLIPS LH	40.00	
32	1 PC REAR WINDSCREEN SEAL	60.00	
33	1 PC REAR WINDSCREEN SEALANT	60.00	
34	1 SET REAR PANEL TRIM CLIPS	40.00	
		1,040.00	1,040.00
Labour			
35	1 TO CHECK WIRING	50.00	
36	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
37	1 TO REMOVE AND REFIT SEAT CUSHION	200.00	
38	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	
39	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
40	1 TO REMOVE AND REFIT PETROL TANK	180.00	
41	1 TO REMOVE AND REFIT INNER TRIM	80.00	
42	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	180.00	
43	1 TO CHECK WHEEL ALIGNMENT	120.00	
44	1 TO SPRAY ANTI RUST	80.00	
45	1 (REAR) TO SPRAY PAINTING	1,500.00	
46	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,600.00	
		4,270.00	4,270.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 3
SINGAPORE 038988

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 11/11/2024
TP Veh Reg No: SBP339R

Estimate No: EST2400434
Date: 12 Nov 2024

Veh Reg No: SMP5613K
Make/Model: MAZDA MAZDA3 4-
DOOR SEDAN 1.5L
SP.6EAT
Chasis No: JM6BM42A8G0328506
Reg. Date: 29/12/2015
Your Ref No: SBP339R

Estimate Repair Cost to Vehicle No :SMP5613K

Quantity	Description	List Price	Amount
		S\$	S\$
	Total		S\$ 13,232.40
	Add GST @ 9%		1,190.92
	Total Amount Payable		S\$ 14,423.32

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND FOUR HUNDRED TWENTY THREE AND CENTS THIRTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE