

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 3
SINGAPORE 038988

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Estimate No: EST2400434

Date: 12 Nov 2024

Veh Reg No: SMP5613K

Make/Model: MAZDA MAZDA3 4-
DOOR SEDAN 1.5L
SP.6EAT

Chasis No: JM6BM42A8G0328506

Reg. Date: 29/12/2015

Your Ref No: SBP339R

Claim Type: Third Party

Accident Date: 11/11/2024

TP Veh Reg No: SBP339R

Estimate Repair Cost to Vehicle No :SMP5613K

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC REAR BUMPER <i>Distorted</i>	1,228.60	✓ 1080
2	1 PC REAR BUMPER REINFORCEMENT <i>Deformed</i>	564.20	✓
3	2 PCS REAR BUMPER SIDE RETAINER <i>Not a LH crumpled</i>	112.80	✗ 56.40
4	1 PC REAR BUMPER REFLECTOR - LH <i>Smashed</i>	106.20	✓
5	1 PC REAR TOWING COVER <i>Missing</i>	51.60	✓
6	1 PC REAR BUMPER LOWER GARNISH LH <i>Not a LH torn</i>	79.60	✗
7	1 PC BOOT LID <i>Repair</i>	1,265.60	✗
8	1 PC BOOTLID LOGO <i>new</i>	85.10	✓
9	1 PC BOOTLID "MAZDA" EMBLEM <i>new</i>	66.20	✓
10	1 PC BOOTLID "SKYACTIV" EMBLEM <i>new</i>	74.40	✓
11	1 PC BOOT LID LAMP LH <i>cut</i>	399.80	✓
12	1 PC BOOT LID RUBBER <i>cut</i>	193.20	✓
13	1 PC REAR FENDER LH <i>Buckled</i>	1,546.30	✓ 1285
14	1 PC REAR FENDER COWLING LH <i>torn</i>	108.60	✓
15	1 PC REAR FENDER LH LOWER SIDE PANEL <i>Not Buckled</i>	262.70	✗
16	1 PC REAR FENDER INNER TRIM LH <i>new</i>	298.70	✗
17	1 PC REAR VENTILATION AIR DUCT <i>new</i>	79.40	✗
18	1 PC REAR WINDSCREEN RUBBER <i>new</i>	124.50	✓
19	1 PC TAIL LAMP LH <i>cut</i>	584.60	✓
20	1 PC TAIL LAMP PANEL LH <i>Deformed</i>	277.40	✓
21	1 PC REAR PANEL <i>Deformed</i>	681.60	✓
22	1 PC REAR PANEL TRIM <i>Deformed</i>	184.00	✓
23	1 PC REAR SPARE TYRE HARDBOARD <i>new</i>	396.10	✗
24	1 PC SPARE TYRE PANEL LH SPONGE <i>torn</i>	297.40	✓
25	1 PC EXHAUST PIPE <i>new</i>	786.20	✗
26	2 PCS EXHAUST PIPE MOUNTING <i>new</i>	48.20	✗
		9,903.00	
	Less 20%	1,980.60	7,922.40

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 3
SINGAPORE 038988

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Estimate No: EST2400434
Date: 12 Nov 2024

Veh Reg No: SMP5613K
Make/Model: MAZDA MAZDA3 4-
DOOR SEDAN 1.5L
SP.6EAT

Chasis No: JM6BM42A8G0328506

Claim Type: Third Party

Reg. Date: 29/12/2015

Accident Date: 11/11/2024

Your Ref No: SBP339R

TP Veh Reg No: SBP339R

Estimate Repair Cost to Vehicle No :SMP5613K

Quantity	Description	List Price	Amount
		SS	SS
Special Net			
27	1 SET REAR BUMPER CLIPS <i>Nce</i>	40.00	30
28	1 SET REVERSE SENSORS <i>Damaged</i>	280.00	20
29	1 PC REAR BOOTLID SPOILER <i>Nce</i>	480.00	X
30	1 SET REAR LH FENDER COWLING CLIPS <i>xlw</i>	40.00	20
31	1 SET REAR FENDER INNER TRIM CLIPS LH <i>Nce Nce</i>	40.00	X
32	1 PC REAR WINDSCREEN SEAL <i>3 sec</i>	60.00	40
33	1 PC REAR WINDSCREEN SEALANT <i>330</i>	60.00	30
34	1 SET REAR PANEL TRIM CLIPS <i>xlw</i>	40.00	10
		1,040.00	1,040.00
Labour			
35	1 TO CHECK WIRING	50.00	30
36	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	✓
37	1 TO REMOVE AND REFIT SEAT CUSHION	200.00	60
38	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	X
39	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	50
40	1 TO REMOVE AND REFIT PETROL TANK	180.00	60
41	1 TO REMOVE AND REFIT INNER TRIM	80.00	60
42	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	180.00	X
43	1 TO CHECK WHEEL ALIGNMENT <i>2740</i>	120.00	X
44	1 TO SPRAY ANTI RUST	80.00	60
45	1 (REAR) TO SPRAY PAINTING	1,500.00	1,100
46	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,600.00	1,200
		4,270.00	4,270.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 3
SINGAPORE 038988

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Estimate No: **EST2400434**
Date: 12 Nov 2024

Veh Reg No: **SMP5613K**
Make/Model: MAZDA MAZDA3 4-
DOOR SEDAN 1.5L
SP.6EAT
Chasis No: JM6BM42A8G0328506
Reg. Date: 29/12/2015
Your Ref No: SBP339R

Claim Type: Third Party
Accident Date: 11/11/2024
TP Veh Reg No: SBP339R

Estimate Repair Cost to Vehicle No :SMP5613K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 13,232.40
		Add GST @ 9%	1,190.92
		Total Amount Payable	<u>S\$ 14,423.32</u>

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND FOUR HUNDRED TWENTY THREE AND CENTS THIRTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

Yur

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
2/8 14/11/24,
10 Days

total: 864792

h/s: 69K

6.9K