

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Zheng Hanyang

Date: 01 Jul 2025

Preliminary Advice

Insured Vehicle No	: SBP339R	Accident Date	: 11/11/2024
TP Vehicle No	: SMP5613K	Assignment Date	: 13/11/2024
Make	: MAZDA 3	Est. Duration of Repair	: 10
Date of Inspection	: 14/11/2024		
Inspection At	: KANG CAR REPAIRERS PTE LTD (HQ) NO 1 KAKI BUKIT AVE 6, #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,232.40
Revised Amount	:S\$	8,647.92
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,647.92
Lump Sum Repair	:S\$	6,900.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.