

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110275/UPA3Q2
Date: 06/02/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_05
Claimant Vehicle No : SMZ7312M Insured Vehicle No : GBH405A
Date of Loss: 12/11/2024 Nature of Claim: TP Claim No: MFL2024D0013410

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMZ7312M
Make & Model: AUDI TT, 2.0 COUPE (A) Engine No: CES010223
Reg. Date: 14/07/2011 (Man. Year: 2011) Chassis No: TRUZZZ8J9B1020006
Colour: Black Odometer: 104298 km
Engine Capacity: 1984 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R17 Rear Tyre Size: 245/45 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,953.93	5,834.03	6,119.90	51.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	1,320.00	690.00	34.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,963.93	7,154.03	6,809.90	48.77
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	13,963.93	5,700.00	8,263.93	59.18
+ GST 9.00/9.00% (S\$)	1,256.75	513.00	743.75	59.18
Nett Amount (S\$)	15,220.68	6,213.00	9,007.68	59.18
+ Car Rental (6.0 x S\$140.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		7,080.25		
Global Sum Settlement (S\$)		7,000.00		

INSPECTION

Date of Assignment: 14/11/2024
Date Inspected: 14/11/2024 Inspected At: LEE BROTHERS AUTOMOTIVE PTE. LTD. (HQ)
1 Kaki Bukit Ave 6, #02-47 Autobay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Dec 2024)
Parts:	M1-COUPE	AUDI TT 2.0 COUPE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ7312M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	2,173.42 FL	*2,108.00 FL
2	1		*FRONT BUMPER SIDE BRACKER RH	Not Necessary	121.50 FL	*- FL
3	1		*FRONT BUMPER FOG LAMP	Not Necessary	281.45 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER	Not Necessary	181.63 FL	*- FL
5	1		*FRONT BUMPER SPONGE	Not Necessary	260.62 FL	*- FL
6	1		*FRONT BONNET	Repair	2,895.37 FL	*- FL
7	1		*FRONT FENDER RH	Cracked	1,085.65 FL	*805.30 FL
8	1		*FRONT FENDER BRACKET	Not Necessary	110.25 FL	*- FL
9	1		*FRONT FENDER INNER SHIELD	Not Necessary	286.43 FL	*- FL
10	1		*FRONT HEADLAMP RH	Cracked	3,253.62 FL	*2,680.62 FL
11	1		*FRONT HEADLAMP CONTROL UNIT	Not Necessary	841.33 FL	*- FL
12	1		*FRONT SUPPORT PANEL	Cracked	965.50 FL	*855.00 FL
13	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
14	1		*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	60.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					12,576.77	6,478.92
- List Item Discount on L Items 5.00/10.00% (\$\$)					622.84	644.89
Total Parts (\$\$)					11,953.93	5,834.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT WIRING	New	50.00	20.00
2	TO TUFF KOTE	New	80.00	20.00
3	TO PUTTY ,SPRAY PAINT & POLISH AFFECTED PARTS	New	1,080.00	680.00
4	TO PANEL BEAT ,CUT ,WELD ,REMOVE & REPLACE DAMAGE PARTS	New	800.00	600.00
Gross Labour Cost (\$\$)			2,010.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >