



Final Report

Estimate No. :
Date Estimated : #####
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -

Soh Hsiu Hsien
306A Punggol Place
#15-37

Singapore 821306

- ACCOUNT -

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNP7138R	WBA70DY0908B98430	30/08/2021	318i Sedan	3890

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper panel, rear bottom trim panel, rear mounting, rear diffuser include carrying out other necessary repairs caused by the accident	850.00		850.00
To respray rear bumper	1,038.00		1,038.00
To remove old PDC assembly, replace damaged parts and reconnect to bumper include conducting checks for proper function	177.00		177.00
To check electrical wiring system and lightings at the rear section for proper function	177.00		177.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER TRIM PANEL BOTTOM (MSP)	239.65	1.00	0.00	239.65
REAR BUMPER MOUNTING (MSP)	156.90	1.00	0.00	156.90
REAR BUMPER TRIM PANEL (MSP/MPA PDC	1,665.30	1.00	0.00	1,665.30
# REAR DIFFUSER	81.85	1.00	0.00	81.85

SUPPLEMENTARY ITEMS

Total Labour :	2,322.00
Total Parts :	2,143.70
Total Labour & Parts (before GST) :	4,465.70
Deduction for Excess :	
Total Repair Costs less Excess:	4,465.70
GST @9%:	401.91
Grand Total :	4,867.61

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

