



> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	821A
<b>Vehicle Details</b>	
Vehicle No.:	SCK8838D
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Jun 2024
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1ZR528526
Chassis No.:	MR053REH104538097
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	10 Sep 2015
First Registration Date:	10 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$19,589.00 9794
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Sep 2025
PARF Rebate Amount:	\$10,773.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	09 Sep 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,498.00
COE Rebate Amount:	\$6,913.00
<b>Total Rebate Amount:</b>	<b>\$17,686.00</b>
<b>Message</b>	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 27 Jun 2024


OK



## CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

All Accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

CERTIFICATE NO.: D22MPC0007781_01		COVER: COMPREHENSIVE
1. Index Mark and Registration Number of Vehicle	: SCK8838D	
Chassis No	: MR053REH104538097	
2. Name of Policyholder	: ANG SEE WANG (HONG SIYUAN)	
3. Effective date of Insurance	: 10 Sep 2023	
4. Expiry date of Insurance	: 09 Sep 2024	
5. Persons or Classes of Persons entitled to drive*	<p>(a) The Policyholder The Policyholder may also drive a Motor Car not belonging to or hired (under a hire purchase agreement or otherwise) to him/her or his/her employer or his/her partner.</p> <p>(b) Any other person who is driving on the Policyholder's order or with his/her permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle</p>	
6. Limitations as to use*	<p>Use only for social, domestic and pleasure purposes and for the Policyholder's business.</p> <p><b>The Policy does not cover</b></p> <p>a) Use for hire or reward. b) Use for racing, pace-making, reliability trial, speed-testing. c) Use for the carriage of goods other than samples in connection with any trade or business. d) Use for any purpose in connection with the Motor Trade.</p> <p>*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.</p>	
Insured & Name Drivers Excess Section I	SGD	600.00
Unnamed drivers Excess Section I	SGD	1,100.00
Windscreen Excess	SGD	100.00
Hire Purchase Company	: N.A	
FOR DRIVERS BELOW 21 YEARS OR ABOVE 69 YEARS OF AGE &/OR LESS THAN 2 YEARS SINGAPORE DRIVING LICENCE, ADDITIONAL EXCESS OF \$2500/- ON SECTION I WILL BE APPLICABLE.		
I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).		
Agent/Broker : A000038/M Plus Consultancy		<p>For India International Insurance Pte Ltd</p>  <p>Nalini Venugopal MD &amp; CEO</p>
Date of Issue : 04/09/2023 11:14:42		
MX1-Private Car (Insured Driving)		

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7239821A



ANG SEE WANG  
(HONG SIYUAN)  
洪思远

Race  
CHINESE

Date of Birth  
24-10-1972

Sex  
M

Country of Birth  
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S7239821A

Name:  
ANG SEE WANG  
(HONG SIYUAN)

Birth Date: 24 Oct 1972  
Issue Date: 11 Mar 2020




INSURED & DRIVER OF : SCK 8838 D

3135447



NRIC No. S7239821A



Blood Group: A+ Date of issue: 11-03-2000

16 JALAN TARI PAYONG  
SINGAPORE 799262

NRIC No: S7239821A Date: 19/05/2014


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight  $\leq$  3000kg with  $\leq$  7 passengers, exclusive of driver; and other motor vehicles with unladen weight  $\leq$  2500kg 21 Dec 1994

NP 428A

Licence No: S7239821A





# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3149/06/24

Your Ref: \_\_\_\_\_

Date: 26th June 2024

The Claim's Manager  
Motor Claims Dept.  
INDIA INTERNATIONAL INSURANCE PTE. LTD.  
6, Raffles Quay, #22-00, S(048580)

Name Of Insured : Mr Ang See Wan  
Date Of Accident : 24/06/24 (13:30hrs)  
Policy Number : D22MPC0007781\_01

Not Authorized  
him  
moss  
28/6/24  
4 hrs  
1/55  
Weight. The 1st.

Estimate cost of repair to TOYOTA COROLLA ALTIS 1.6 (A) Saloon - SCK 8838 D

1 pc boot lid o/s reflector	CN	\$ 391.70	/
1 pc boot lid lock	SN	432.50	X
1 pc boot lid 'Corolla Altis' emblem	nm	93.80	/
1 pc boot lid weatherstrip		190.10	?
1 pc boot lid lock stricker	11	29.20	X
1 pc rear bumper	De	620.60	/
10 pcs rear bumper clips	nm	57.00	/
2 pcs rear bumper o/s & n/s top retainer	11	131.20	X
2 pcs rear bumper o/s & n/s side retainer		238.60	?
1 pc rear bumper reinforcement		432.50	?
2 pcs rear bumper reinforcement o/s & n/s stay		172.40	?
1 set rear bumper reverse sensor (Original)	CN	398.40	/
1 set rear bumper reverse sensor holder		109.80	X
1 pc rear end panel		727.70	?
1 pc rear end panel top garnish		261.60	?
6 pcs rear end panel top garnish clips		37.20	X

Less 25%  
\$ 4,324.30  
\$ 1,081.08

\$ 3,243.22

1 pc rear number plate & frame

50.00 S.N X

To wiring check up for affected wiring system.

60.00 20

To remove & refix carpet, floor board cover, floor mat, garnish, spare tyre, tool set & necessary parts.

120.00 60

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear floor board panel, rear end panel & necessary parts, to weld, renew & align above parts.

1,100.00 600

To putty & respray painting on all affected accident parts.

1,300.00 800

\$ 5,873.22  
=====

Dollars : Five Thousand Eight Hundred Seventy Three And Cents Twenty Two Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To clearly damaged parts, before painting
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: