

ONE GARAGE PTE LTD

8 KAKI BUKIT AVENUE 4 #03-33 PREMIER@KAKI BUKIT
SINGAPORE 415875
TEL: 96311088

TO	: NTUC	DATE	: 18/11/2024
VEHICLE NO	: SNJ7647U (2020)		
VEHICLE MODEL	: MERCEDES BENZ A200		Xiao Chan.
CHASSIS NO	: W1K1771872J198790		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>torn</i>	1	\$ 1,341.00	\$ 1,341.00
2	FRONT BUMPER SIDE HOLDER <i>new</i>	2	\$ 96.00	\$ 192.00
3	FRONT BUMPER SENSOR <i>new</i>	1	\$ 285.00	\$ 285.00
4	FRONT BUMPER LOGO <i>new</i>	1	\$ 89.00	\$ 89.00
5	HEADLAMP <i>new</i>	1	\$ 3,301.00	\$ 3,301.00

TOTAL PRICE: \$ 5,208.00
LESS 10% \$ 520.80
SUB TOTAL PRICE: \$ 4,687.20

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER SIDE FIN (SET) <i>Missing</i>	1	\$ 500.00	\$ 500.00
3	FRONT BUMPER FOG LAMP COVER TOP GARNISH (SET) <i>lost</i>	1	\$ 700.00	\$ 700.00
4	FRONT BUMPER LOWER GARNISH <i>Behind</i>	1	\$ 1,000.00	\$ 1,000.00
5	FRONT WHEEL RIM <i>3 x 4</i>	1	\$ 1,280.00	\$ 1,280.00
6	FRONT TYRE <i>2 new</i>	1	\$ 350.00	\$ 350.00

TOTAL: \$ 3,880.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 400.00	200	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 400.00	200	
3	WIRING CHECK	\$ 50.00	X	
4	TO REMOVE FRONT BUMPER SENSOR	\$ 100.00	50	

TOTAL: \$ 950.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 8,567.20

TOTAL LABOUR COST: \$ 950.00

TOTAL REPAIR COST: \$ 9,517.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2887

2/3: 2.31C ✓
03 Days