

CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 62431373

Reg. No: 201538764H

Email: CA3SERVICES@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT	<i>Xiao Chun</i>
DATE:	12-11-24	
CLAIM TYPE:	T/P CLAIM	
TO:	INCOME	
VEHICLE DETAILS		
VEHICLE NO:	SMM8554T	
MAKE & MODEL:	MIT ATTRAGE	
CHASSIS NO:		
ACCIDENT DETAILS		
DATE:	12 November, 2024	
TIME:	1420HRS	
THIRD PARTY REQUESTOR:	JACK LI	

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Buckled</i>	1	\$ 1,050.50	\$ 1,050.50
2	BOOTLID LOGO <i>new</i>	1	\$ 80.00	\$ 80.00
3	BOOTLID ATTRAGE EMBLEM <i>new</i>	1	\$ 60.00	\$ 60.00
4	BOOTLID MIVEC TECHNOLOGY EMBLEM <i>new</i>	1	\$ 60.00	\$ 60.00
5	BOOTLID C&C EMBLEM <i>new</i>	1	\$ 60.00	\$ 60.00
6	BOOTLID LOCK <i>new</i>	1	\$ 230.00	\$ 230.00
7	BOOTLID WEATHERSTRIP <i>new</i>	1	\$ 280.00	\$ 280.00
8	BOOTLID ANTENNA SWITCH <i>new Buckled</i>	1	\$ 235.00	\$ 235.00
9	BOOTLID BUZZEL <i>new</i>	1	\$ 203.50	\$ 203.50
10	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 160.00	\$ 160.00
11	REAR BUMPER <i>new</i>	1	\$ 850.30	\$ 850.30
12	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 69.40	\$ 138.80
13	REAR BUMPER AIRVENT <i>new</i>	1	\$ 90.00	\$ 90.00
14	REAR BUMPER AIRVENT COVER <i>new</i>	1	\$ 140.00	\$ 140.00
15	TAILLAMP <i>LH cover</i>	2	\$ 530.00	\$ 1,060.00
16	TAILLAMP PANEL <i>new</i>	2	\$ 211.00	\$ 422.00
17	REAR FENDER <i>new</i>	2	\$ 890.00	\$ 1,780.00
18	REAR FENDER INNER TRIM <i>new</i>	2	\$ 420.00	\$ 840.00
19	END PANEL <i>new</i>	1	\$ 670.00	\$ 670.00
20	END PANEL TOP GARNISH <i>new</i>	1	\$ 190.00	\$ 190.00

TOTAL PRICE \$ 8,600.10

3502
315180

789
135
765
35
335
483

LESS 10% \$ 860.01
 SUB TOTAL PRICE \$ 7,740.09

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR NUMBER PLATE <i>Not rev</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS SET <i>Rev</i>	1	\$ 22.00	\$ 22.00
3	REAR FENDER INNER TRIM CLIPS SET <i>Not rev</i>	1	\$ 20.00	\$ 20.00
4	REAR END PANEL TOP GARNISH CLIPS SET <i>Not rev</i>	1	\$ 20.00	\$ 20.00
5	REAR END PANEL INSULATION SEAL <i>Rev</i>	1	\$ 120.00	\$ 120.00
6	REVERSE SENSOR <i>Rev</i>	1	\$ 220.00	\$ 220.00

Rear Bumper spoiler Rehd

TOTAL \$ 452.00
~~\$ 1,000~~ 700

1002

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,800.00	\$ 1,800.00
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,800.00	\$ 1,800.00
3	TUFF COAT	1	\$ 200.00	\$ 200.00
4	WIRING CHECK	1	\$ 80.00	\$ 80.00
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 280.00	\$ 280.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00
8	REMOVE AND REFIX WINDSCREEN	1	\$ 120.00	\$ 120.00

1750 TOTAL \$ 4,480.00

ESTIMATE REPORT

TOTAL PARTS COST \$ 8,192.09
 TOTAL LABOUR COST \$ 4,480.00
 TOTAL REPAIR COST \$ 12,672.09

APPROVED DETAILS: LKK Auto Consultants hence notify

SURVEYOR: the Repairer of the following:
 CONTACT NO.:
 PART BY PART/LUMP SUM
 NO. OF DAYS

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- All prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature

Address L/S 14/11/24
06 Days

Total: 5903.80
L/S: 4.7K