

Atan Kenneth
Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SDE 9771A
TP/China

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
 3 ANSON ROAD
 16-00 SPRINGLEAF TOWER
 SINGAPORE 079909
 TEL: 63896111 FAX: 62221033
 ATTN: Motor Claim Department
 WS Ref: TP/CHINA
 Claim Type: Third Party
 Accident Date: 12/11/2024
 TP Veh Reg No: YN3033R

Claim No: ES2400946
 Estimate No: ES2400946/YISHUN
 Date: 14 Nov 2024
 Policy No: 5137759173-01
 Veh Reg No: SDE9771A
 Make/Model: VOLKSWAGEN JETTA 1.4
 Chassis No: WVVZZZ1KZAM128677
 Engine No: CAX509995
 Reg. Date: 12/08/2010

NOT Withdraw
1/1 Sep & 28 Oct
Return After Paint

Estimate Repair Cost to Vehicle No : SDE9771A

Pages: 1/1


Description	U/Price	Quantity	Cost S\$	Amount S\$
Cost Plus				
1 REAR BUMPER	600.00	1 PC	600.00	
2 REAR BUMPER REINFORCEMENT	350.00	1 PC	350.00	
3 REAR BUMPER SPONGE	75.00	1 PC	75.00	
4 REAR BOOT	900.00	1 PC	900.00	
5 REAR BOOT LOGO	45.00	1 PC	45.00	
6 REAR BOOT EMBLEM 'JETTA'	75.00	1 PC	75.00	
7 REAR BOOT EMBLEM 'TSI'	40.00	1 PC	40.00	
8 REAR BOOT LH REFLECTOR	125.00	1 PC	125.00	
9 LH TAILLAMP	200.00	1 PC	200.00	
10 REAR PANEL	450.00	1 PC	450.00	
			2,860.00	
	Add 10%		286.00	3,146.00
Labour				
11 REMOVE & REFIX REAR BUMPER ASSY, REAR BOOT, RENEW REAR PANEL, KNOCKING & REPAIR REAR LH FENDER & REALIGN THE SAME	750.00	1 LA	750.00	
12 PUTTY & RESPRAY ON REAR LH FENDER, REAR BOOT, REAR PANEL, REAR BUMPER	850.00	1 LA	850.00	
13 REMOVE & REFIX REVERSE CAMERA, REVERSE SENSOR & RESET SYSTEM	40.00	1 LA	40.00	
14 RUSTPROOFING	30.00	1 LA	30.00	
				1,670.00
			Total	S\$ 4,816.00
			Add GST @ 9%	433.44
			Total Amount payable	S\$ 5,249.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

ADD 10%


AUTHORISED SIGNATURE

1985
198.50
2183.50
1320

3503.50
45 # 2,800/